

Case Report

Status: Open - In Progress

Title: MS Allision/ 37 46. N 122 18. W/071630ZNOV07

Incident Type/Subtype: MS Allision

SMC/IC: Sector San Francisco

Contains Activities:

A. Activity ID:3095059 Title: Resource Sortie - Patrol (Non-Security)

B. Activity ID:3094822 Title: Incident Management - MS Allision/ 37 46. N 122 18. W/071630ZNOV07 Incident Summary:

C. Activity ID:3095056 Title: Resource Sortie - Patrol (Non-Security)

D. Activity ID:3095621 Title: Resource Sortie - Patrol (Non-Security)

E. Activity ID:3095968 Title: Vessel Inspection/PSC - ISM Exam

F. Activity ID:3095046 Title: Resource Sortie - Patrol (Non-Security)

G. Activity ID:3094631 Title: Incident Management - MS Allision/ 37 46. N 122 18. W/071630ZNOV07 Incident Summary: The container ship Cosco Busan got underway from Oakland berth 56 for sea, unit Romeo was piloting the ship. Sector San Francisco Vessel Traffic Service noticed the vessel making an unusual turn. Traffic asked the pilot what his intentions were, the pilot stated that he intendeds to transit under the Delta- Echo span of the Bay Bridge. Traffic stated that the vessel was on a heading that looked unusual; the pilot stated that his instruments had a different reading. Shortly after traffic was contacted by the pilot stating that he had just struck the bridge. VTS SF NTFD the Sector San Francisco Command Center (SCC) and the California Transportation Authority (CAL TRANS). CAL TRANS dispatched inspectors/engineers to the allision site and RPTD no damage to the bridge structure w/ the exception of the fendering system. Following the allision, COSCO BUSAN proceeded to San Francisco Bay anchorage (ANC) 7 where San Francisco Bar Pilot Unit "R" was relieved by unit "37." 37 later piloted SUBJ VSL FM ANC 7 to ANC 9. COTP Order 07-074 was issued by COTP SF and RCVD by VTS SF requiring COSCO BUSAN to remain in ANC 9 until released by COTP Order. COTP 07-074 was later ammended to permit SUBJ VSL to depart anchorage for the Hanjin Terminals at the Port of Oakland, CA. As of 101747U NOV 07 M/V COSCO BUSAN remained moored alongside of Hanjin Berth 56 Oakland Ca. Activity Closed - Sector San Francisco / VTS

MISLE Attachments:

Documents: : P 080357Z NOV 07 ZUI ASN.doc; : 7b5060ee5c0c.pdf; : 11 07 07 07 43 45 Traffic Report Prepare UW.wav; : 11 07 07 08 08 35 Cosco Busan Underway.wav; : 11 07 07 08 52 50 Cosco Busan Anchorage 7.way; : 11 07 07 08 55 06 Encinal Report of Debris, way; : 11 07 07 09 00 41 Securite Call.way; : 11 07 07 09 01 38 Unit 37 Aboard Cosco Busan.way; : 11 07 2007 08 31 42 Report of Bridge Allision.wav; : 11 07 07 08 32 Int Report to SCC - Perez.wav; : 11 07 07 08 33 58 Unit R Phone Call -Cooper.way; : 11 07 07 08 33 Int Call to CALTRANS - Unit R Call Perez.way; : 11 07 07 08 49 Pete McIssac Fuel in Water.way; : 11 07 07_09 39 13 Mr Perez - CALTRANS.way; : 11 07 07 09 42 55 Mr Perez - Sean Kelly.wav; : 11 07 07 09 15 27 Mr Perez - KCBS.wav; : 11 07 07 09 14 32 Lynn Marie Reporting Oily Sheen.way; : 11 07 07 09 09 SCC Call to VTS - No Departure Order for CB.way; : 11 07 07 09 09 SCC Call to VTS - No Departure Order for CB.way; : 11 07 07 09 09 34 Part 2 Unit 37 Call to VTS.way; : 11 07 07 09 09 34 Part 2 Unit 37 Call to VTS.way; : 11 07 07 08 57 Unit R Disconnected Tel Call to VTS.way; : 11 07 07 08 49 Pete McIssac Fuel in Water.way; : 11 07 07 08 55 Pete McIssac Fuel Recovery Request - Unit R Oil in Water Unit 37 to Board CB - VTS OPS notified.way; : Cosco Busan.avi; : Cosco Busan - MISLE #381733.msg; : 11 07 2007 08 55 56 Phone Conversations.wav; Photograph: 11 07 2007 08 30 00 Allision.bmp; : P 110323Z NOV 07 PSN 589028H32.doc; : P 100531Z NOV 07 ZUI ASN-P01314000016.doc;

H. Activity ID:3095030 Title: Incident Investigation - M/V COSCO BUSAN/ALLISION/POLLUTION

I. Activity ID:3096205 Title: Incident Management - Incident Summary:

Print for Activity: 3094631

Case Title: MS Allision/ 37 46. N 122 18. W/071630ZNOV07

Case Number: 381733 Activity Number: 3094631

Date/TimeSubject(s)Entered By071630ZNOV07<no subject>Cooper, Drew P.

Message

Initial Notification - SF BAR PILOT UNIT R WAS PILOTING THE M/V COSCO BUSAN UNDER THE OAKLAND BAY BRIDGE AND STUCK THE DELTA TOWER OF THE BRIDGE.

Date/Time Subject(s) Entered By
071630ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

SCC rovd rpt from VTS stating that the M/V Cosco Busan had struck the delta tower of the bay bridge while transiting outbound from Oakland. The vsl is now at anchorage 7. VTS reports they will contact CALTRANS

Date/Time Subject(s) Entered By
071631ZNOV07 COSCO BUSAN; COTA, JOHN Flesher, Gabriel
A.

Message

Date/Time Subject(s) Entered By 071633ZNOV07 <no subject> Cooper, Drew P.

Message

SEC SF VTS BRIEFED CAL TRANS: ALLISION TO THE EAST SIDE OF THE DELTA TOWER OF THE OAKLAND BAY BRIDGE. REPORTED DAMAGE TO PILEINGS.

Date/Time Subject(s) Entered By
071636ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

SCC issued an SMIB about the COSCO BUSAN making contact with the Bay Bridge. SMIB warned all vsls to keep a 100yrd distance from the vsl and to transit the area with caution. SMIB is to be issued every 15 minutes.

Date/Time Subject(s) Entered By
071637ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

SU briefed ENS Hopper

Date/Time Subject(s) Entered By
071640ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

SCC briefed Mr. Sulouff at D11

Date/Time Subject(s) Entered By 071646ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

Briefed STA SF for launch to investigate damage to bridge and vessel

Date/Time Subject(s) Entered By
071648ZNOV07 <no subject> Cooper, Drew P.

Message

PIER DEBRIS AND FUEL IN WATER DID NOT KNOW THE FULL EXTENT OF DAMAGE. RECOMMENDED CONTACT ARMY CORP OF ENGINEERS AND RESPOND TO DEBRIS IN WATER.

Date/TimeSubject(s)Entered By071650ZNOV07COSCO BUSANCooper, Drew P.

Message

COSCO BUSAN RPTD TO VTS: ANCHORED IN ANCHORAGE 7.

Date/Time Subject(s) Entered By

071650ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

Briefed IMD, MST2 Anderson will be departing to investigate spill

Date/Time Subject(s) Entered By

071650ZNOV07 <no subject> bidowski, andrea .

Message

SCC was notified by NRC (report # 853865) that there was oil in the water caused by the M/V Cosco Busan. IMD was briefed via phone.

Date/Time Subject(s) Entered By 071655ZNOV07 COTA, JOHN; HOBURG, ELLSWORTH F Cooper, Drew P.

Message

MR HOBURG (SF BARY PILOT UNIT: 37) STATED HE HAD RELIEVED CAPTAIN JOHN COTA (SF BAR PILOT UNIT: R).

Date/Time Subject(s) Entered By
071659ZNOV07 <no subject> Cooper, Drew P.

Message

VTS SF SENT SECURITE BCST TO INFORM VESSELS OF MINIMUM WAKE AROUND COSCO BUSAN IN ANC 7.

 Date/Time
 Subject(s)
 Entered By

 071704ZNOV07
 UTB - 41392
 Boyd, Ryan E.

Message

Response Resource Requested

Date/Time Subject(s) Entered By 071704ZNOV07 UTB - 41392 Boyd, Ryan E.

Message

UTB - 41392 USCG - CG STA SAN FRANCISCO Launched

Date/Time Subject(s) Entered By 071705ZNOV07 <no subject> Cooper, Drew P.

Message

VTS SF NTFD THE ACOE OF THE DEBRIS IN THE WATER SOUTH OF THE OAKLAND BAY BRIDGE.

Date/TimeSubject(s)EnteredBy071710ZNOV07LYNN MARIECooper, Drew P.

Message

TUB LYNN MARIE INFORMED VTS THAT THE TUG HAD SPOTTED FUEL AND DEBRIS FROM YERBA BUENA ISLAND TO THE ALPHA TOWER OF THE OAKLAND BAY BRIDGE.

Date/Time Subject(s) Entered By 071713ZNOV07 UTB - 41392 Boyd, Ryan E.

Message

UTB - 41392 USCG - CG STA SAN FRANCISCO On Scene at 071713Z NOV 07

Date/Time Subject(s) Entered By 071713ZNOV07 UTB - 41392 Boyd, Ryan E.

Message

Target Located at 071713Z NOV 07

Date/Time Subject(s) Entered By 071713ZNOV07 UTB - 41392 Boyd, Ryan E.

Message

UTB - 41392 USCG - CG STA SAN FRANCISCO Alongside

Date/Time Subject(s) Entered By
071722ZNOV07 <no subject> Cooper, Drew P.

Message

ACOE STATED THAT THEY WOULD SEND ASSESTS TO ASSIST IN DEBRIS CLEAN UP.

Date/Time Subject(s) Entered By

071722ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

contacted agent who stated that OSRO had been notified

Date/Time Subject(s) Entered By 071723ZNOV07 HOBURG, ELLSWORTH F Cooper, Drew P.

Message

INQUIRED IF ANY OF THE OIL RESPONSE BOATS HAVE CHECKED IN FOR THE COSCO BUSAN. NO OIL RESPONSE VESSELS HAVE CHECKED IN AS OF YET. VTS QUERRIED THE PILOT ON FUEL LEAKAGE SITUATION. PILOT'S RESPONSE WAS THE SHIP'S CREW HAS SECURED THE FUEL SPILL.

Date/TimeSubject(s)Entered By071730ZNOV07<no subject>NAGLE, RUSSELL P.

Message

conducted virtual brief

Date/Time Subject(s) Entered By
071739ZNOV07 <no subject> Cooper, Drew P.

Message

CAL TRANS RPTD TO VTS THAT INVESTIGATORS WERE ON SEEN TO CHECK THE STURCTURAL DAMGAE TO THE TOWER.

Date/Time Subject(s) Entered By
071745ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

SCC initiated CIC; CIC request denied due to the issue being a local issue.

Date/Time Subject(s) Entered By
071745ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

PO Anderson reports the sounding tube appears bent; resulting in uncertain information regarding fuel discharge.

Date/Time Subject(s) Entered By 071754ZNOV07 HOBURG, ELLSWORTH F Cooper, Drew P.

Message

REQUESTED TO SHIFT THE VESSEL TO ANCHORAGE 9 DUE TO DRAFT CONCERNS, THE VESSEL IS DRAWING 40'4" ANCHORAGE 7 IS NOT AN IDEAL ANCHORAGE FOR THE VESSEL. SEC SF SMC AUTHORIZED.

Date/Time Subject(s) Entered By
071754ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

COSCO BUSAN enr Anchoarage 9

Date/Time Subject(s) Entered By
071757ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

CGC Tern briefed for launch

Date/Time Subject(s) Entered By 071758ZNOV07 COSCO BUSAN Cooper, Drew P.

Message

SEC SF VTS NOTIFIED VSL THAT VESSEL HAD TO MAINTAIN ATLEAST 1 NM DISTANCE FROM ANY ANCHORED VESSEL.

Date/TimeSubject(s)Entered By071807ZNOV07COSCO BUSAN; HOBURG, ELLSWORTH FCooper, Drew P.

Message

UNIT 37 ONBOARD THE COSCO BUSAN CONTACTED SEC SF VTS PREPARING TO DEPART ANCHORAGE 7 FOR ANCHORAGE 9.

Date/Time Subject(s) Entered By 071812ZNOV07 <no subject> bidowski, andrea .

Message

We received a call from Danny Herod at O'Briens stating that an OSRO Team is getting assembled.

 Date/Time
 Subject(s)
 Entered By

 071817ZNOV07
 RBS - 25501
 Boyd, Ryan E.

Message

Response Resource Requested

Date/Time Subject(s) Entered By 071817ZNOV07 RBS - 25501 Boyd, Ryan E.

Message

RBS - 25501 USCG - CG STA SAN FRANCISCO Launched

Date/Time Subject(s) Entered By 071822ZNOV07 <no subject> Cooper, Drew P.

Message

NOTIFIED THAT M/V COSCO BUSAN UNDERWAY FOR ANCHORAGE 9

Date/Time Subject(s) Entered By
071822ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

CGC Tern assumes PATCOM

 Date/Time
 Subject(s)
 Entered By

 071825ZNOV07
 RBS - 25501
 Boyd, Ryan E.

Message

RBS - 25501 USCG - CG STA SAN FRANCISCO On Scene at 071825Z NOV 07

 Date/Time
 Subject(s)
 Entered By

 071825ZNOV07
 RBS - 25501
 Boyd, Ryan E.

Message

Target Located at 071825Z NOV 07

 Date/Time
 Subject(s)
 Entered By

 071825ZNOV07
 RBS - 25501
 Boyd, Ryan E.

Message

RBS - 25501 USCG - CG STA SAN FRANCISCO Alongside

Date/Time Subject(s) Entered By
071830ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

The O'Brien's Group notified the SCC that they are the Qualified Individual and will be coordinating the response for the spill. By 1830Z they had already dispatched MSRC, NRC to the scene with four boom boats and two skimmers. OES, Fish and Game, OSPR, and local stakeholders were contacted by SCC and Sector IMD. SCC dispatched PSC, I/O, and IMD team to the vessel to conduct survey and investigation.

Date/TimeSubject(s)EnteredBy071914ZNOV07COSCO BUSANCooper, Drew P.

Message

VESSEL ANCHORED IN ANCHORAGE 9.

Date/Time Subject(s) Entered By
072000ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

Sector stood up Unified Command at YBI. IMD dispatched SCAT teams to conduct shoreline assessment throughout the afternoon. MSST boats were dispatched to conduct safety zone around the vessel, and enforce the security zone around the bridge abuttments

Date/Time Subject(s) Entered By 072007ZNOV07 UTB - 41392 Boyd, Ryan E.

Message

UTB - 41392 USCG - CG STA SAN FRANCISCO Departed Scene

 Date/Time
 Subject(s)
 Entered By

 072010ZNOV07
 UTB - 41392
 Boyd, Ryan E.

Message

UTB - 41392 USCG - CG STA SAN FRANCISCO Sortie Ended

Date/Time Subject(s) Entered By
072104ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

Briefed ASSF for launch

 Date/Time
 Subject(s)
 Entered By

 072110ZNOV07
 RBS - 25406
 Boyd, Ryan E.

Message

Response Resource Requested

 Date/Time
 Subject(s)
 Entered By

 072110ZNOV07
 RBS - 25406
 Boyd, Ryan E.

Message

RBS - 25406 USCG - CG STA SAN FRANCISCO Launched

Date/Time Subject(s) Entered By 072120ZNOV07 RBS - 25406 Boyd, Ryan E.

Message

RBS - 25406 USCG - CG STA SAN FRANCISCO On Scene at 072120Z NOV 07

Date/Time Subject(s) Entered By 072120ZNOV07 RBS - 25406 Boyd, Ryan E.

Message

Target Located at 072120Z NOV 07

 Date/Time
 Subject(s)
 Entered By

 072120ZNOV07
 RBS - 25406
 Boyd, Ryan E.

Message

RBS - 25406 USCG - CG STA SAN FRANCISCO Alongside

Date/Time Subject(s) Entered By 072130ZNOV07 RBS - 25406 Boyd, Ryan E.

Message

RBS - 25406 USCG - CG STA SAN FRANCISCO Departed Scene

Date/TimeSubject(s)Entered By072138ZNOV07RBS - 25406Boyd, Ryan E.

Message

RBS - 25406 USCG - CG STA SAN FRANCISCO Sortie Ended

 Date/Time
 Subject(s)
 Entered By

 072204ZNOV07
 RBS - 25501
 Boyd, Ryan E.

Message

RBS - 25501 USCG - CG STA SAN FRANCISCO Departed Scene

Date/Time Subject(s) Entered By 072241ZNOV07 UTB - 41392 housey, keith m.

Message

Response Resource Requested

Date/Time Subject(s) Entered By 072241ZNOV07 UTB - 41392 housey, keith m.

Message

UTB - 41392 USCG - CG STA SAN FRANCISCO Launched

Date/Time Subject(s) Entered By
072255ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

ASSF HELO 6516 has experienced a flight casualty and will not be able to land at the confined space at YBI. Directed to RTB.

Date/Time Subject(s) Entered By

072318ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

STA SF UTB has a 10min ETA.

Date/Time Subject(s) Entered By 072333ZNOV07 UTB - 41392 housey, keith m.

Message

UTB - 41392 USCG - CG STA SAN FRANCISCO On Scene at 072333Z NOV 07

Date/TimeSubject(s)Entered By072337ZNOV07<no subject>NAGLE, RUSSELL P.

Message

SCC Updated SMIB to warn mariners to keep a lookout for various amounts of oil and diesel in the water.

watti.

Date/Time Subject(s) Entered By 80000ZNOV07 <no subject> bidowski, andrea.

Message

Issued COTP Order # 07-074.

Date/Time Subject(s) Entered By
080003ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

STA GG Reports NPS is closing their beaches effected by the oil spill. D11 Notified.

Date/Time Subject(s) Entered By
080021ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

Briefed D11 about NPS plans to close beaches

Date/Time Subject(s) Entered By 080121ZNOV07 UTB - 41392 housey, keith m.

Message

UTB - 41392 USCG - CG STA SAN FRANCISCO Sortie Ended

Date/TimeSubject(s)Entered By080202ZNOV07COSCO BUSANFlesher, Gabriel

Α.

Message

VTS SF IRO COTP ORDER 07-074 - COSCO BUSAN to remain in ANC 9 until order is adjusted or rescinded and damage assessment required by VSL's classification society.

Date/Time Subject(s) Entered By
081628ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

CG6516 A/B for overflight

Date/Time Subject(s) Entered By
081758ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

Briefed ASSF for 2nd overflight

Date/Time Subject(s) Entered By
081915ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

SCC ntfd Dl1 of the request for support from the Pacific Strike Team

Date/Time Subject(s) Entered By
081940ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

ASSF picked up SEC SF CO for overflight

Date/Time Subject(s) Entered By

082000ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

SCC ntfd D11 of the incident command post contact numbers

Date/Time Subject(s) Entered By
082214ZNOV07 RBS - 25501 Boyd, Ryan E.

Message

RBS - 25501 USCG - CG STA SAN FRANCISCO Sortie Ended

Date/TimeSubject(s)Entered By090405ZNOV07COSCO BUSANFlesher, Gabriel

Α.

Message

VTS SF IRO COTP ORDER 07-074 Ammendment 01 for COSCO BUSAN. VSL is permitted to depart ANC 9 for OAK 56. VSL required to have 02 tug escort, minimize list while offloading cargo, shall not depart until COTP SF approves repair proposal.

Date/TimeSubject(s)Entered By100200ZNOV07COSCO BUSAN; KELSO, ARNOLDFlesher, Gabriel

Α.

Message

Unit 18 A/B M/V COSCO BUSAN RPTS preparing to depart ANC 9 for OAK 56 IAW COTP Order 07-074.

Date/Time Subject(s) Entered By
100534ZNOV07 <no subject> Grant, Luke J.

Message

100030R - PACAREA - D11 - SEC SAN FRAN - M/V COSCO BUSAN - UPDATE - First light overflights were conducted to determine/assess which areas needed to be skimmed. Eleven skimmers have been actively skimming areas within the affected counties of San Francisco, Marin, Alameda, and Contra Costa. A total of 38,200 feet of boom has been set in these counties with emphasis on 10 known environmentally sensitive sites. Weather conditions continue to promote effective skimming ops inside and outside of the Golden Gate. To date, 8000 to 9500 gallons of product have been recovered. During the last 12 hours, approximately 11,000 gallons of oily water mixture was recovered. Twenty-four shoreline contractor cleanup teams have been employed/assigned at the 22 affected beaches. Seven cubic yards of oily solid material have been collected from impacted beaches. Five Shoreline Cleanup Assessment Teams have been organized and deployed to assess shoreline conditions and provide cleanup recommendations. To date, 94 birds were oiled and are being treated. 28 birds have died. Vessel has safely shifted from Anchorage 9 to Oakland Berth 56. The COTP has detained the vessel under the International Safety Management (ISM) code. Case Pends. V/r, LTJG Grant, LANT/D5 MHLS Watch

Date/TimeSubject(s)Entered By100556ZNOV07COSCO BUSAN; KELSO, ARNOLDFlesher, Gabriel

A.

Message

SF Bar Pilot unit 18 RPTS SUBJ VSL moored Hanjin Terminal Berth 56, Oakland CA.

Date/TimeSubject(s)Entered By110028ZNOV07<no subject>Flesher, Gabriel

Α.

Message

Incident Management Activety 3094631 - Final Review Conducted by OSC G. Flesher (SEC SF - VTS).

Sequence of Events.

11/07/2007 16:30:00 (Known): Initial Notification - SF BAR PILOT UNIT R WAS PILOTING THE M/V COSCO BUSAN UNDER THE OAKLAND BAY BRIDGE AND STUCK THE DELTA TOWER OF THE BRIDGE.

Action Class: Response Communication

Sub-Type: Initial Notification

Location:

Subject(s) and Details:

Name Type Status Role

<no subject> Other

Details Filed: Notification

Incident Detail/Location

Incident Type: MS: Allision

Incident Date/Time: 11/07/2007 4:30:00 PM

Notification Method: VHF/FM (other than Channel 16)

Date/Time Notified: 11/07/2007 4:30:00 PM

Specific Notification Problem: No

Incident Location:

Address: City, St, Zip:

Province/Country:

Latitude: 37 46.0 N Longitude: 122 18.0 W

General Location/Affected Area

Reporting Party

Name: John Cota

Callback Phone: Cell Phone: Location:

Address:
City, ST, Zip:
Province/Country:

Facility Name: Organization:

Latitude: 0 Longitude: 0

General Location:

Involved Subjects

Incident Description

SF BAR PILOT UNIT 9 WAS PILOTING THE M/V COSCO BUSAN UNDER THE OAKLAND BAY BRIDGE AND STUCK THE DELTA TOWER OF THE BRIDGE.

11/07/2007 16:30:00 (Known): SCC rcvd rpt from VTS stating that the M/V Cosco Busan had struck the delta tower of the bay bridge while transiting outbound from Oakland. The vsl is now at anchorage 7. VTS reports they will contact CALTRANS

Action Class: Response Communication

Sub-Type:

Location:

Subject(s) and Details:

Name Type Status Role

<no subject> Other

Details Filed: None

11/07/2007 16:31:00 (Known):

Event Class: Allision Sub-Type: Broadside

Location:

Subject(s) and Details:

Name <u>Type</u> <u>Status</u> <u>Role</u>

COTA, JOHN Party Responsible Party

Details Filed: None

COSCO BUSAN Vessel Acknowledged Pollution Source

Details Filed: Collision Details

Location of Impact:
Above/Below WaterLine:
Vessel Course:
Vessel Speed:
Steering Functional:
Propulsion Functional:
Port Midships
Above
300 True
9.5 Knots
Fully
Fully
Fully

Fuel On Board: Cargo On Board:

Cargo Name Quantity

Additional Information: SUBJ VSL allidded w/the San Francisco Oakland Bay Bridge

11/07/2007 16:33:00 (Known): SEC SF VTS BRIEFED CAL TRANS: ALLISION TO THE EAST SIDE OF THE DELTA TOWER OF THE OAKLAND BAY BRIDGE. REPORTED DAMAGE TO PILEINGS.

Action Class: Response Communication Sub-Type: Briefing - Other Agency

Location:

Subject(s) and Details:

Name Type Status Role

<no subject> Other

Details Filed: None

11/07/2007 16:36:00 (Known): SCC issued an SMIB about the COSCO BUSAN making contact with the Bay Bridge. SMIB warned all vsls to keep a 100yrd distance from the vsl and to transit the area with caution. SMIB is to be issued every 15 minutes.

Action Class: Response Communication

Sub-Type:

Location:

Subject(s) and Details:

<u>Name</u> <u>Type</u> <u>Status</u> <u>Role</u>

<no subject> Other

Details Filed: None

11/07/2007 16:37:00 (Known): SU briefed ENS Hopper

Action Class: Response Communication

Sub-Type: Location:

Subject(s) and Details:

Name <u>Type</u> <u>Status</u> <u>Role</u>

<no subject> Other

Details Filed: None

11/07/2007 16:40:00 (Known): SCC briefed Mr. Sulouff at D11

Action Class: Response Communication

Sub-Type: Briefing - District

Location:

Subject(s) and Details:

Name Type Status Role

<no subject> Other

Details Filed: None

11/07/2007 16:46:00 (Known): Briefed STA SF for launch to investigate damage to bridge and vessel

Action Class: Response Communication
Sub-Type: Briefing - SRU/Response Team

Location:

Subject(s) and Details:

Name Type Status Role

<no subject> Other

Details Filed: None

11/07/2007 16:48:00 (Known): PIER DEBRIS AND FUEL IN WATER DID NOT KNOW THE FULL EXTENT OF DAMAGE. RECOMMENDED CONTACT ARMY CORP OF ENGINEERS AND RESPOND TO DEBRIS IN WATER.

Action Class: Response Communication Sub-Type: Briefing - Other Agency

Location:

Subject(s) and Details:

Name Type Status Role

<no subject> Other

Details Filed: None

11/07/2007 16:50:00 (Known): COSCO BUSAN RPTD TO VTS: ANCHORED IN ANCHORAGE 7.

Action Class: Resource Action Sub-Type: Resource Diverted

Location:

Subject(s) and Details:

Name Type Status Role

COSCO BUSAN Vessel Acknowledged Pollution Source

Details Filed: None

11/07/2007 16:50:00 (Known): SCC was notified by NRC (report # 853865) that there was oil in the water caused by the M/V Cosco Busan. IMD was briefed via phone.

Action Class: Response Communication

Sub-Type: Location:

Subject(s) and Details:

Name Type Status Role

<no subject> Other

Details Filed: None

11/07/2007 16:50:00 (Known): Briefed IMD, MST2 Anderson will be departing to investigate spill

Action Class: Response Communication

Sub-Type: Location:

Subject(s) and Details:

Name Type Status Role

<no subject> Other

Details Filed: None

11/07/2007 16:55:00 (Known): MR HOBURG (SF BARY PILOT UNIT: 37) STATED HE HAD RELIEVED CAPTAIN JOHN COTA (SF BAR PILOT UNIT: R).

Condition Class: Personnel Condition

Sub-Type: Person

Location:

Subject(s) and Details:

Name Type Status Role

COTA, JOHN Party Responsible Party

Details Filed: None

HOBURG, Party Watchstander

ELLSWORTH F
Details Filed: None

11/07/2007 16:59:00 (Known): VTS SF SENT SECURITE BCST TO INFORM VESSELS OF MINIMUM WAKE AROUND COSCO BUSAN IN ANC 7.

Action Class: Response Communication Sub-Type: Issue Notice to Mariners

Location:

Subject(s) and Details:

Name <u>Type</u> <u>Status</u> <u>Role</u>

<no subject> Other

Details Filed: None

11/07/2007 17:05:00 (Known): VTS SF NTFD THE ACOE OF THE DEBRIS IN THE WATER SOUTH OF THE OAKLAND BAY BRIDGE.

Action Class: Response Communication Sub-Type: Briefing - Other Agency

Location:

Subject(s) and Details:

Name Type Status Role

<no subject> Other

Details Filed: None

11/07/2007 17:10:00 (Known): TUB LYNN MARIE INFORMED VTS THAT THE TUG HAD SPOTTED FUEL AND DEBRIS FROM YERBA BUENA ISLAND TO THE ALPHA TOWER OF THE OAKLAND BAY BRIDGE.

Action Class: Response Communication

Sub-Type: Initial Notification

Location:

Subject(s) and Details:

Name Type Status Role

LYNN MARIE Vessel Transiting Vicinity of Primary Subject

Details Filed: None

11/07/2007 17:22:00 (Known): ACOE STATED THAT THEY WOULD SEND ASSESTS TO ASSIST IN DEBRIS CLEAN UP.

Action Class: Response Communication
Sub-Type: Briefing - Other Agency

Location:

Subject(s) and Details:

<u>Name</u> <u>Type</u> <u>Status</u> <u>Role</u>

<no subject> Other

Details Filed: None

11/07/2007 17:22:00 (Known): contacted agent who stated that OSRO had been notified

Action Class: Response Communication

Sub-Type: Location:

Subject(s) and Details:

Name Type Status Role

<no subject> Other

Details Filed: None

11/07/2007 17:23:00 (Known): INQUIRED IF ANY OF THE OIL RESPONSE BOATS HAVE CHECKED IN FOR THE COSCO BUSAN. NO OIL RESPONSE VESSELS HAVE CHECKED IN AS OF YET. VTS QUERRIED THE PILOT ON FUEL LEAKAGE SITUATION. PILOT'S RESPONSE WAS THE SHIP'S CREW HAS SECURED THE FUEL SPILL.

Action Class: Response Communication Sub-Type: Briefing - Other Agency

Location:

Subject(s) and Details:

Name Type Status Role

HOBURG, Party Watchstander

ELLSWORTH F
Details Filed: None

11/07/2007 17:30:00 (Known): conducted virtual brief

Action Class: Response Communication

Sub-Type: Location:

Subject(s) and Details:

<u>Name</u> <u>Type</u> <u>Status</u> <u>Role</u>

<no subject> Other

Details Filed: None

11/07/2007 17:39:00 (Known): CAL TRANS RPTD TO VTS THAT INVESTIGATORS WERE ON SEEN TO CHECK THE STURCTURAL DAMGAE TO THE TOWER.

Action Class: Response Communication
Sub-Type: Briefing - Other Agency

Location:

Subject(s) and Details:

<u>Name</u> <u>Type</u> <u>Status</u> <u>Role</u>

<no subject> Other

Details Filed: None

11/07/2007 17:45:00 (Known): SCC initiated CIC; CIC request denied due to the issue being a local issue.

Action Class: Response Communication

Sub-Type: Location:

Subject(s) and Details:

<u>Name</u> <u>Type</u> <u>Status</u> <u>Role</u>

<no subject> Other

Details Filed: None

11/07/2007 17:45:00 (Known): PO Anderson reports the sounding tube appears bent; resulting in uncertain information regarding fuel discharge.

Action Class: Response Communication

Sub-Type: Location:

Subject(s) and Details:

Name Type Status Role

<no subject> Other

Details Filed: None

11/07/2007 17:54:00 (Known): COSCO BUSAN enr Anchoarage 9

Action Class: Response Communication

Sub-Type: Location:

Subject(s) and Details:

Name Type Status Role

<no subject> Other

Details Filed: None

11/07/2007 17:54:00 (Known): REQUESTED TO SHIFT THE VESSEL TO ANCHORAGE 9 DUE TO DRAFT CONCERNS, THE VESSEL IS DRAWING 40'4" ANCHORAGE 7 IS NOT AN IDEAL ANCHORAGE FOR THE VESSEL. SEC SF SMC AUTHORIZED.

Action Class: Response Communication

Sub-Type: Briefing - SMC/IC

Location:

Subject(s) and Details:

<u>Name</u> <u>Type</u> <u>Status</u> <u>Role</u>

HOBURG, Party Watchstander

ELLSWORTH F
Details Filed: None

11/07/2007 17:57:00 (Known): CGC Tern briefed for launch

Action Class: Response Communication
Sub-Type: Briefing - SRU/Response Team

Location:

Subject(s) and Details:

<u>Name</u> <u>Type</u> <u>Status</u> <u>Role</u>

<no subject> Other

Details Filed: None

11/07/2007 17:58:00 (Known): SEC SF VTS NOTIFIED VSL THAT VESSEL HAD TO MAINTAIN ATLEAST 1 NM DISTANCE FROM ANY ANCHORED VESSEL.

Action Class: Response Communication

Sub-Type: Briefing - SMC/IC

Location:

Subject(s) and Details:

Name Type Status Role

COSCO BUSAN Vessel Acknowledged Pollution Source

Details Filed: None

11/07/2007 18:07:00 (Known): UNIT 37 ONBOARD THE COSCO BUSAN CONTACTED SEC SF VTS PREPARING TO DEPART ANCHORAGE 7 FOR ANCHORAGE 9.

Condition Class: Vessel Operation Status

Sub-Type: Location:

Subject(s) and Details:

Name Type Status Role

HOBURG, Party Watchstander

ELLSWORTH F

Details Filed: None

COSCO BUSAN Vessel Acknowledged

Pollution Source

Details Filed: None

11/07/2007 18:12:00 (Known): We received a call from Danny Herod at O'Briens stating that an OSRO Team is getting assembled.

Action Class: Response Communication

Sub-Type: Location:

Subject(s) and Details:

<u>Name</u> <u>Type</u> <u>Status</u> <u>Role</u>

<no subject> Other

Details Filed: None

11/07/2007 18:22:00 (Known): CGC Tern assumes PATCOM

Action Class: Response Communication

Sub-Type: Location:

Subject(s) and Details:

<u>Name</u> <u>Type</u> <u>Status</u> <u>Role</u>

<no subject> Other

Details Filed: None

11/07/2007 18:22:00 (Known): NOTIFIED THAT M/V COSCO BUSAN UNDERWAY FOR ANCHORAGE 9

Action Class: Response Communication

Sub-Type: Briefing - SMC/IC

Location:

Subject(s) and Details:

Name Type Status Role

<no subject> Other

Details Filed: None

11/07/2007 18:30:00 (Known): The O'Brien's Group notified the SCC that they are the Qualified Individual and will be coordinating the response for the spill. By 1830Z they had already dispatched MSRC, NRC to the scene with four boom boats and two skimmers. OES, Fish and Game, OSPR, and local stakeholders were contacted by SCC and Sector IMD. SCC dispatched PSC, I/O, and IMD team to the vessel to conduct survey and investigation.

Action Class: Response Communication

Sub-Type: Location:

Subject(s) and Details:

<u>Name</u> <u>Type</u> <u>Status</u> <u>Role</u>

<no subject> Other

Details Filed: None

11/07/2007 19:14:00 (Known): VESSEL ANCHORED IN ANCHORAGE 9.

Action Class: Response Communication

Sub-Type: Location:

Subject(s) and Details:

<u>Name</u> <u>Type</u> <u>Status</u> <u>Role</u>

COSCO BUSAN Vessel Acknowledged Pollution Source

Details Filed: None

11/07/2007 20:00:00 (Known): Sector stood up Unified Command at YBI. IMD dispatched SCAT teams to conduct shoreline assessment throughout the afternoon. MSST boats were dispatched to conduct safety zone around the vessel, and enforce the security zone around the bridge abuttments

Action Class: Response Communication

Sub-Type: Location:

Subject(s) and Details:

<u>Name</u> <u>Type</u> <u>Status</u> <u>Role</u>

<no subject> Other

Details Filed: None

11/07/2007 21:04:00 (Known): Briefed ASSF for launch

Action Class: Response Communication

Sub-Type: Briefing - SRU/Response Team

Location:

Subject(s) and Details:

Name Type Status Role

<no subject> Other

Details Filed: None

11/07/2007 22:55:00 (Known): ASSF HELO 6516 has experienced a flight casualty and will not be able to land at the confined space at YBI. Directed to RTB.

Action Class: Response Communication

Sub-Type: Briefing - SRU/Response Team

Location:

Subject(s) and Details:

<u>Name</u> <u>Type</u> <u>Status</u> <u>Role</u>

<no subject> Other

Details Filed: None

11/07/2007 23:18:00 (Known): STA SF UTB has a 10min ETA.

Action Class: Response Communication
Sub-Type: Briefing - SRU/Response Team

Location:

Subject(s) and Details:

<u>Name</u> <u>Type</u> <u>Status</u> <u>Role</u>

<no subject> Other

Details Filed: None

11/07/2007 23:37:00 (Known): SCC Updated SMIB to warn mariners to keep a lookout for various amounts of oil and diesel in the water.

Action Class: Response Communication

Sub-Type: Location:

Subject(s) and Details:

<u>Name</u> <u>Type</u> <u>Status</u> <u>Role</u>

<no subject> Other

Details Filed: None

11/08/2007 0:00:00 (Known): Issued COTP Order # 07-074.

Action Class: Response Communication

Sub-Type: Location:

Subject(s) and Details:

Name Type Status Role

<no subject> Other

Details Filed: None

11/08/2007 0:03:00 (Known): STA GG Reports NPS is closing their beaches effected by the oil spill. D11 Notified.

Action Class: Response Communication

Sub-Type: Location:

Subject(s) and Details:

Name Type Status Role

<no subject> Other

Details Filed: None

11/08/2007 0:21:00 (Known): Briefed D11 about NPS plans to close beaches

Action Class: Response Communication

Sub-Type: Location:

Subject(s) and Details:

<u>Name</u> <u>Type</u> <u>Status</u> <u>Role</u>

<no subject> Other

Details Filed: None

11/08/2007 2:02:00 (Known): VTS SF IRO COTP ORDER 07-074 - COSCO BUSAN to remain in ANC 9 until order is adjusted or rescinded and damage assessment required by VSL's classification society.

Action Class: Response Communication

Sub-Type: Briefing - SMC/IC

Location:

Subject(s) and Details:

Name <u>Type</u> <u>Status</u> <u>Role</u>

COSCO BUSAN Vessel Acknowledged Pollution Source

Details Filed: None

11/08/2007 16:28:00 (Known): CG6516 A/B for overflight

Action Class: Response Communication

Sub-Type: Location:

Subject(s) and Details:

Name Type Status Role

<no subject> Other

Details Filed: None

11/08/2007 17:58:00 (Known): Briefed ASSF for 2nd overflight

Action Class: Response Communication

Sub-Type: Location:

Subject(s) and Details:

Name <u>Type</u> <u>Status</u> <u>Role</u>

<no subject> Other

Details Filed: None

11/08/2007 19:15:00 (Known): SCC ntfd D11 of the request for support from the Pacific Strike Team

Action Class: Response Communication

Sub-Type: Location:

Subject(s) and Details:

<u>Name</u> <u>Type</u> <u>Status</u> <u>Role</u>

<no subject> Other

Details Filed: None

11/08/2007 19:40:00 (Known): ASSF picked up SEC SF CO for overflight

Action Class: Response Communication

Sub-Type: Location:

Subject(s) and Details:

<u>Name</u> <u>Type</u> <u>Status</u> <u>Role</u>

<no subject> Other

Details Filed: None

11/08/2007 20:00:00 (Known): SCC ntfd D11 of the incident command post contact numbers

Action Class: Response Communication

Sub-Type: Location:

Subject(s) and Details:

Name Type Status Role

<no subject> Other

Details Filed: None

11/09/2007 4:05:00 (Known): VTS SF IRO COTP ORDER 07-074 Ammendment 01 for COSCO BUSAN. VSL is permitted to depart ANC 9 for OAK 56. VSL required to have 02 tug escort, minimize list while offloading cargo, shall not depart until COTP SF approves repair proposal.

Action Class: Impose Operational Control

Sub-Type: COTP Order

Location:

Subject(s) and Details:

Name Type Status Role

COSCO BUSAN Vessel Acknowledged Pollution Source

Details Filed: None

11/10/2007 2:00:00 (Known): Unit 18 A/B M/V COSCO BUSAN RPTS preparing to depart ANC 9 for OAK 56 IAW COTP Order 07-074.

Condition Class: Vessel Operation Status

Sub-Type: Location:

Subject(s) and Details:

<u>Name</u> <u>Type</u> <u>Status</u> <u>Role</u>

KELSO, ARNOLD Party Watchstander

Details Filed: None

COSCO BUSAN Vessel Acknowledged Pollution Source

Details Filed: None

11/10/2007 5:56:00 (Known): SF Bar Pilot unit 18 RPTS SUBJ VSL moored Hanjin Terminal Berth 56, Oakland CA.

Condition Class: Vessel Operation Status

Sub-Type: Location:

Subject(s) and Details:

<u>Name</u> <u>Type</u> <u>Status</u> <u>Role</u>

KELSO, ARNOLD Party Watchstander

Details Filed: None

COSCO BUSAN Vessel Acknowledged

Pollution Source

Details Filed: None

11/11/2007 0:28:00 (Known): Incident Management Activety 3094631 - Final Review Conducted by OSC G. Flesher (SEC SF - VTS).

Action Class: Conduct Activity

Sub-Type: Location:

Subject(s) and Details:

Name Type Status Role

<no subject> Other

Details Filed: None

Print for Activity: 3094822

Case Title: MS Allision/ 37 46. N 122 18. W/071630ZNOV07

Case Number: 381733 Activity Number: 3094822

Date/TimeSubject(s)Entered By071630ZNOV07<no subject>Cooper, Drew P.

Message

Initial Notification - SF BAR PILOT UNIT R WAS PILOTING THE M/V COSCO BUSAN UNDER THE OAKLAND BAY BRIDGE AND STUCK THE DELTA TOWER OF THE BRIDGE.

Date/Time Subject(s) Entered By
071630ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

SCC rovd rpt from VTS stating that the M/V Cosco Busan had struck the delta tower of the bay bridge while transiting outbound from Oakland. The vsl is now at anchorage 7. VTS reports they will contact CALTRANS

Date/Time Subject(s) Entered By
071631ZNOV07 COSCO BUSAN; COTA, JOHN Flesher, Gabriel
A.

Message

Date/Time Subject(s) Entered By 071633ZNOV07 <no subject> Cooper, Drew P.

Message

SEC SF VTS BRIEFED CAL TRANS: ALLISION TO THE EAST SIDE OF THE DELTA TOWER OF THE OAKLAND BAY BRIDGE. REPORTED DAMAGE TO PILEINGS.

Date/Time Subject(s) Entered By
071636ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

SCC issued an SMIB about the COSCO BUSAN making contact with the Bay Bridge. SMIB warned all vsls to keep a 100yrd distance from the vsl and to transit the area with caution. SMIB is to be issued every 15 minutes.

Date/Time Subject(s) Entered By
071637ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

SU briefed ENS Hopper

Date/Time Subject(s) Entered By
071640ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

SCC briefed Mr. Sulouff at D11

Date/Time Subject(s) Entered By
071646ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

Briefed STA SF for launch to investigate damage to bridge and vessel

Date/Time Subject(s) Entered By
071648ZNOV07 <no subject> Cooper, Drew P.

Message

PIER DEBRIS AND FUEL IN WATER DID NOT KNOW THE FULL EXTENT OF DAMAGE. RECOMMENDED CONTACT ARMY CORP OF ENGINEERS AND RESPOND TO DEBRIS IN WATER.

Date/TimeSubject(s)Entered By071650ZNOV07COSCO BUSANCooper, Drew P.

Message

COSCO BUSAN RPTD TO VTS: ANCHORED IN ANCHORAGE 7.

Date/Time Subject(s) Entered By

071650ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

Briefed IMD, MST2 Anderson will be departing to investigate spill

Date/Time Subject(s) Entered By

071650ZNOV07 <no subject> bidowski, andrea .

Message

SCC was notified by NRC (report # 853865) that there was oil in the water caused by the M/V Cosco Busan. IMD was briefed via phone.

Date/Time Subject(s) Entered By 071655ZNOV07 COTA, JOHN; HOBURG, ELLSWORTH F Cooper, Drew P.

Message

MR HOBURG (SF BARY PILOT UNIT: 37) STATED HE HAD RELIEVED CAPTAIN JOHN COTA (SF BAR PILOT UNIT: R).

Date/Time Subject(s) Entered By
071659ZNOV07 <no subject> Cooper, Drew P.

Message

VTS SF SENT SECURITE BCST TO INFORM VESSELS OF MINIMUM WAKE AROUND COSCO BUSAN IN ANC 7.

 Date/Time
 Subject(s)
 Entered By

 071704ZNOV07
 UTB - 41392
 Boyd, Ryan E.

Message

Response Resource Requested

Date/Time Subject(s) Entered By 071704ZNOV07 UTB - 41392 Boyd, Ryan E.

Message

UTB - 41392 USCG - CG STA SAN FRANCISCO Launched

Date/Time Subject(s) Entered By 071705ZNOV07 <no subject> Cooper, Drew P.

Message

VTS SF NTFD THE ACOE OF THE DEBRIS IN THE WATER SOUTH OF THE OAKLAND BAY BRIDGE.

Date/TimeSubject(s)EnteredBy071710ZNOV07LYNN MARIECooper, Drew P.

Message

TUB LYNN MARIE INFORMED VTS THAT THE TUG HAD SPOTTED FUEL AND DEBRIS FROM YERBA BUENA ISLAND TO THE ALPHA TOWER OF THE OAKLAND BAY BRIDGE.

Date/Time Subject(s) Entered By 071713ZNOV07 UTB - 41392 Boyd, Ryan E.

Message

UTB - 41392 USCG - CG STA SAN FRANCISCO On Scene at 071713Z NOV 07

Date/Time Subject(s) Entered By 071713ZNOV07 UTB - 41392 Boyd, Ryan E.

Message

Target Located at 071713Z NOV 07

Date/Time Subject(s) Entered By 071713ZNOV07 UTB - 41392 Boyd, Ryan E.

Message

UTB - 41392 USCG - CG STA SAN FRANCISCO Alongside

Date/Time Subject(s) Entered By
071722ZNOV07 <no subject> Cooper, Drew P.

Message

ACOE STATED THAT THEY WOULD SEND ASSESTS TO ASSIST IN DEBRIS CLEAN UP.

Date/Time Subject(s) Entered By

071722ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

contacted agent who stated that OSRO had been notified

Date/Time Subject(s) Entered By 071723ZNOV07 HOBURG, ELLSWORTH F Cooper, Drew P.

Message

INQUIRED IF ANY OF THE OIL RESPONSE BOATS HAVE CHECKED IN FOR THE COSCO BUSAN. NO OIL RESPONSE VESSELS HAVE CHECKED IN AS OF YET. VTS QUERRIED THE PILOT ON FUEL LEAKAGE SITUATION. PILOT'S RESPONSE WAS THE SHIP'S CREW HAS SECURED THE FUEL SPILL.

Date/TimeSubject(s)Entered By071730ZNOV07<no subject>NAGLE, RUSSELL P.

Message

conducted virtual brief

Date/Time Subject(s) Entered By
071739ZNOV07 <no subject> Cooper, Drew P.

Message

CAL TRANS RPTD TO VTS THAT INVESTIGATORS WERE ON SEEN TO CHECK THE STURCTURAL DAMGAE TO THE TOWER.

Date/Time Subject(s) Entered By
071745ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

SCC initiated CIC; CIC request denied due to the issue being a local issue.

Date/Time Subject(s) Entered By
071745ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

PO Anderson reports the sounding tube appears bent; resulting in uncertain information regarding fuel discharge.

Date/Time Subject(s) Entered By 071754ZNOV07 HOBURG, ELLSWORTH F Cooper, Drew P.

Message

REQUESTED TO SHIFT THE VESSEL TO ANCHORAGE 9 DUE TO DRAFT CONCERNS, THE VESSEL IS DRAWING 40'4" ANCHORAGE 7 IS NOT AN IDEAL ANCHORAGE FOR THE VESSEL. SEC SF SMC AUTHORIZED.

Date/Time Subject(s) Entered By
071754ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

COSCO BUSAN enr Anchoarage 9

Date/Time Subject(s) Entered By
071757ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

CGC Tern briefed for launch

Date/Time Subject(s) Entered By 071758ZNOV07 COSCO BUSAN Cooper, Drew P.

Message

SEC SF VTS NOTIFIED VSL THAT VESSEL HAD TO MAINTAIN ATLEAST 1 NM DISTANCE FROM ANY ANCHORED VESSEL.

Date/TimeSubject(s)Entered By071807ZNOV07COSCO BUSAN; HOBURG, ELLSWORTH FCooper, Drew P.

Message

UNIT 37 ONBOARD THE COSCO BUSAN CONTACTED SEC SF VTS PREPARING TO DEPART ANCHORAGE 7 FOR ANCHORAGE 9.

Date/Time Subject(s) Entered By 071812ZNOV07 <no subject> bidowski, andrea .

Message

We received a call from Danny Herod at O'Briens stating that an OSRO Team is getting assembled.

 Date/Time
 Subject(s)
 Entered By

 071817ZNOV07
 RBS - 25501
 Boyd, Ryan E.

Message

Response Resource Requested

Date/Time Subject(s) Entered By 071817ZNOV07 RBS - 25501 Boyd, Ryan E.

Message

RBS - 25501 USCG - CG STA SAN FRANCISCO Launched

Date/Time Subject(s) Entered By 071822ZNOV07 <no subject> Cooper, Drew P.

Message

NOTIFIED THAT M/V COSCO BUSAN UNDERWAY FOR ANCHORAGE 9

Date/Time Subject(s) Entered By
071822ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

CGC Tern assumes PATCOM

 Date/Time
 Subject(s)
 Entered By

 071825ZNOV07
 RBS - 25501
 Boyd, Ryan E.

Message

RBS - 25501 USCG - CG STA SAN FRANCISCO On Scene at 071825Z NOV 07

 Date/Time
 Subject(s)
 Entered By

 071825ZNOV07
 RBS - 25501
 Boyd, Ryan E.

Message

Target Located at 071825Z NOV 07

 Date/Time
 Subject(s)
 Entered By

 071825ZNOV07
 RBS - 25501
 Boyd, Ryan E.

Message

RBS - 25501 USCG - CG STA SAN FRANCISCO Alongside

Date/Time Subject(s) Entered By
071830ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

The O'Brien's Group notified the SCC that they are the Qualified Individual and will be coordinating the response for the spill. By 1830Z they had already dispatched MSRC, NRC to the scene with four boom boats and two skimmers. OES, Fish and Game, OSPR, and local stakeholders were contacted by SCC and Sector IMD. SCC dispatched PSC, I/O, and IMD team to the vessel to conduct survey and investigation.

Date/TimeSubject(s)EnteredBy071914ZNOV07COSCO BUSANCooper, Drew P.

Message

VESSEL ANCHORED IN ANCHORAGE 9.

Date/Time Subject(s) Entered By
072000ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

Sector stood up Unified Command at YBI. IMD dispatched SCAT teams to conduct shoreline assessment throughout the afternoon. MSST boats were dispatched to conduct safety zone around the vessel, and enforce the security zone around the bridge abuttments

Date/Time Subject(s) Entered By 072007ZNOV07 UTB - 41392 Boyd, Ryan E.

Message

UTB - 41392 USCG - CG STA SAN FRANCISCO Departed Scene

 Date/Time
 Subject(s)
 Entered By

 072010ZNOV07
 UTB - 41392
 Boyd, Ryan E.

Message

UTB - 41392 USCG - CG STA SAN FRANCISCO Sortie Ended

Date/Time Subject(s) Entered By
072104ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

Briefed ASSF for launch

 Date/Time
 Subject(s)
 Entered By

 072110ZNOV07
 RBS - 25406
 Boyd, Ryan E.

Message

Response Resource Requested

 Date/Time
 Subject(s)
 Entered By

 072110ZNOV07
 RBS - 25406
 Boyd, Ryan E.

Message

RBS - 25406 USCG - CG STA SAN FRANCISCO Launched

Date/Time Subject(s) Entered By 072120ZNOV07 RBS - 25406 Boyd, Ryan E.

Message

RBS - 25406 USCG - CG STA SAN FRANCISCO On Scene at 072120Z NOV 07

Date/Time Subject(s) Entered By 072120ZNOV07 RBS - 25406 Boyd, Ryan E.

Message

Target Located at 072120Z NOV 07

 Date/Time
 Subject(s)
 Entered By

 072120ZNOV07
 RBS - 25406
 Boyd, Ryan E.

Message

RBS - 25406 USCG - CG STA SAN FRANCISCO Alongside

Date/Time Subject(s) Entered By 072130ZNOV07 RBS - 25406 Boyd, Ryan E.

Message

RBS - 25406 USCG - CG STA SAN FRANCISCO Departed Scene

Date/TimeSubject(s)Entered By072138ZNOV07RBS - 25406Boyd, Ryan E.

Message

RBS - 25406 USCG - CG STA SAN FRANCISCO Sortie Ended

 Date/Time
 Subject(s)
 Entered By

 072204ZNOV07
 RBS - 25501
 Boyd, Ryan E.

Message

RBS - 25501 USCG - CG STA SAN FRANCISCO Departed Scene

Date/Time Subject(s) Entered By 072241ZNOV07 UTB - 41392 housey, keith m.

Message

Response Resource Requested

Date/Time Subject(s) Entered By 072241ZNOV07 UTB - 41392 housey, keith m.

Message

UTB - 41392 USCG - CG STA SAN FRANCISCO Launched

Date/Time Subject(s) Entered By
072255ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

ASSF HELO 6516 has experienced a flight casualty and will not be able to land at the confined space at YBI. Directed to RTB.

Date/Time Subject(s) Entered By

072318ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

STA SF UTB has a 10min ETA.

Date/Time Subject(s) Entered By 072333ZNOV07 UTB - 41392 housey, keith m.

Message

UTB - 41392 USCG - CG STA SAN FRANCISCO On Scene at 072333Z NOV 07

Date/TimeSubject(s)Entered By072337ZNOV07<no subject>NAGLE, RUSSELL P.

Message

SCC Updated SMIB to warn mariners to keep a lookout for various amounts of oil and diesel in the water.

watti.

Date/Time Subject(s) Entered By 80000ZNOV07 <no subject> bidowski, andrea.

Message

Issued COTP Order # 07-074.

Date/Time Subject(s) Entered By
080003ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

STA GG Reports NPS is closing their beaches effected by the oil spill. D11 Notified.

Date/Time Subject(s) Entered By
080021ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

Briefed D11 about NPS plans to close beaches

Date/Time Subject(s) Entered By 080121ZNOV07 UTB - 41392 housey, keith m.

Message

UTB - 41392 USCG - CG STA SAN FRANCISCO Sortie Ended

Date/TimeSubject(s)Entered By080202ZNOV07COSCO BUSANFlesher, Gabriel

Α.

Message

VTS SF IRO COTP ORDER 07-074 - COSCO BUSAN to remain in ANC 9 until order is adjusted or rescinded and damage assessment required by VSL's classification society.

Date/Time Subject(s) Entered By
081628ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

CG6516 A/B for overflight

Date/Time Subject(s) Entered By
081758ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

Briefed ASSF for 2nd overflight

Date/Time Subject(s) Entered By
081915ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

SCC ntfd Dl1 of the request for support from the Pacific Strike Team

Date/Time Subject(s) Entered By
081940ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

ASSF picked up SEC SF CO for overflight

Date/Time Subject(s) Entered By

082000ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

SCC ntfd D11 of the incident command post contact numbers

Date/Time Subject(s) Entered By
082214ZNOV07 RBS - 25501 Boyd, Ryan E.

Message

RBS - 25501 USCG - CG STA SAN FRANCISCO Sortie Ended

Date/TimeSubject(s)Entered By090405ZNOV07COSCO BUSANFlesher, Gabriel

Α.

Message

VTS SF IRO COTP ORDER 07-074 Ammendment 01 for COSCO BUSAN. VSL is permitted to depart ANC 9 for OAK 56. VSL required to have 02 tug escort, minimize list while offloading cargo, shall not depart until COTP SF approves repair proposal.

Date/TimeSubject(s)Entered By100200ZNOV07COSCO BUSAN; KELSO, ARNOLDFlesher, Gabriel

Α.

Message

Unit 18 A/B M/V COSCO BUSAN RPTS preparing to depart ANC 9 for OAK 56 IAW COTP Order 07-074.

Date/Time Subject(s) Entered By
100534ZNOV07 <no subject> Grant, Luke J.

Message

100030R - PACAREA - D11 - SEC SAN FRAN - M/V COSCO BUSAN - UPDATE - First light overflights were conducted to determine/assess which areas needed to be skimmed. Eleven skimmers have been actively skimming areas within the affected counties of San Francisco, Marin, Alameda, and Contra Costa. A total of 38,200 feet of boom has been set in these counties with emphasis on 10 known environmentally sensitive sites. Weather conditions continue to promote effective skimming ops inside and outside of the Golden Gate. To date, 8000 to 9500 gallons of product have been recovered. During the last 12 hours, approximately 11,000 gallons of oily water mixture was recovered. Twenty-four shoreline contractor cleanup teams have been employed/assigned at the 22 affected beaches. Seven cubic yards of oily solid material have been collected from impacted beaches. Five Shoreline Cleanup Assessment Teams have been organized and deployed to assess shoreline conditions and provide cleanup recommendations. To date, 94 birds were oiled and are being treated. 28 birds have died. Vessel has safely shifted from Anchorage 9 to Oakland Berth 56. The COTP has detained the vessel under the International Safety Management (ISM) code. Case Pends. V/r, LTJG Grant, LANT/D5 MHLS Watch

Date/TimeSubject(s)Entered By100556ZNOV07COSCO BUSAN; KELSO, ARNOLDFlesher, Gabriel

A.

Message

SF Bar Pilot unit 18 RPTS SUBJ VSL moored Hanjin Terminal Berth 56, Oakland CA.

Date/TimeSubject(s)Entered By110028ZNOV07<no subject>Flesher, Gabriel

Α.

Message

Incident Management Activety 3094631 - Final Review Conducted by OSC G. Flesher (SEC SF - VTS).

Print for Activity: 3095030

Sequence of Events.

11/07/2007 16:30:00 to 11/07/2007 16:30:00 (Estimated): Initial Notification - SF BAR PILOT UNIT 9 WAS PILOTING THE M/V COSCO BUSAN UNDER THE OAKLAND BAY BRIDGE AND STUCK THE DELTA TOWER OF THE BRIDGE.

Action Type: Other Actions - Reporting/Notifications
Action Class: Report/Notification of Casualty or Incident

Location: Known; US Waters

Description: Incident Location

Latitude: 37 46.0 N Longitude: 122 18.0 W

Subject(s) and Details:

<u>Name</u> <u>Type</u> <u>Status</u> <u>Role</u> Cota, John Party Not at Risk Other

Details Filed: Notification Incident Detail/Location

Incident Type: MS: Allision

Incident Date/Time: 11/07/2007 4:30:00 PM

Notification Method: VHF/FM (other than Channel 16)

Date/Time Notified: 11/07/2007 4:30:00 PM

Specific Notification Problem: No

Incident Location:

Address:

City, St, Zip: Province/Country:

Latitude: 37 46.0 N Longitude: 122 18.0 W

General Location/Affected Area

Reporting Party

Name: John Cota

Callback Phone: Cell Phone: Location:

Address:

City, ST, Zip: Province/Country:

Facility Name: Organization:

Latitude: 0 Longitude: 0

General Location:

Involved Subjects

Incident Description

SF BAR PILOT UNIT 9 WAS PILOTING THE M/V COSCO BUSAN UNDER THE OAKLAND BAY BRIDGE AND STUCK THE DELTA TOWER OF THE BRIDGE.

M/V COSCO BUSAN/ALLISION/POLLUTIONON 11/07/2007

MISLE ACTIVITY NUMBER: 3095030
ORIGINATING UNIT: SECTOR SAN FRANCISCO
MISLE ACTIVITY OWNER: SECTOR SAN FRANCISCO
MISLE ACTIVITY CONTROLLER: SECTOR SAN FRANCISCO
MISLE CASE NUMBER: 381733

I. INCIDENT BRIEF

On November 7, 2007 at approximately 0830 local time, the M/V COSCO BUSAN was transiting under the San Francisco-Oakland Bay Bridge during its outbound transit to sea and allided with the Delta Tower of the bridge on its port bow. The allision severely damaged the hull, allowing oil to discharge into San Francisco Bay. The vessel changed course and proceeded to anchorage to await further survey and investigation.

II. EXECUTIVE SUMMARY

Incident Summary

On November 7, 2007 at approximately 0830 local time, the M/V COSCO BUSAN was transiting under the San Francisco-Oakland Bay Bridge during its outbound transit to sea and allided with the Delta Tower of the bridge on its port bow. The allision severely damaged the hull, allowing oil to discharge into San Francisco Bay. The vessel changed course and proceeded to anchorage to await further survey and investigation.

Incident Involved: Marine Casualty, Reportable

Discharge of Oil

This incident resulted in a discharge or substantial threat of discharge of oil. This report does not limit the discretion of the Director, NPFC, to determine facts, rights and liabilities with respect to any claims, submitted to or by the NPFC, for removal costs and damages under the Oil Pollution Act of 1990.

Level of Investigation: Formal

IMO Classification: Serious Incident

USCG Classification: Major Marine Casualty Was this a Serious Marine Incident? Yes

Was a Marine Board Convened by Commandant? No

Personnel Casualty Summary

Total Missing = 0

Total Dead = 0

Total Injured = 0

Total at Risk, Not Injured = 0

Total People at Risk = 0

Other Personnel (Not at Risk) = 24

Vessel(s) Status Summary

Actual Total Loss(es) = 0

Total Constructive Loss, Salvaged = 0

Total Constructive Loss, Unsalvaged = 0

Damaged = 1

Undamaged = 0

Property Damage Summary/Total Damage

Vessel(s) =\$

Cargo = \$

Facility(s) = \$

Other = \$

* Includes estimates

Waterway Mobility Summary

Vessel Delays (including speed restrictions): None

III. ACTIONS IN RESPONSE TO THIS REPORT

Actions on Recommendations

Safety Alerts

IV. FINDINGS OF FACT

Subjects of the Investigation

Vessels. The following vessels were subjects of this investigation. Particulars for each vessel follow.

Vessel Name:	COSCO BUSAN
Flag:	HONG KONG
Vessel Identification Number:	9231743
Call Sign:	DPSQ
Status:	Damaged
Role:	Involved in a Marine Casualty
Vessel Class, Type, Sub-Type:	General Dry Cargo Ship, Container Ship, General
Gross Tonnage(GRT):	
Net Tonnage(NRT):	
Deadweight Tons:	68086
Length:	901.2
Home/Hailing Port:	HAMBURG, GERMANY
Keel Laid Date:	
Delivery Date:	12/18/2001
Place of Construction:	
Builder Name:	
Propulsion:	Diesel Direct
Horsepower:	77600
Master:	
Classification Society:	GERMANISCHER LLOYD
Owner:	REGAL Stone LTD
	Rm 1603, 16th Floor, MassMutual Tower
	38 Gloucester Rd
	Wanchai,,
	НК
Operator:	
Inspection Subchapter:	
Most Recent Vessel Inspection Activity:	

Facilities. The following facilities were subjects of this investigation. Particulars for each facility follow.

Parties and Organizations. The following people and organizations were subjects of this investigation.

Cota, John	
Status:	Not at Risk
Role:	Other

Gender:
Age:
SSN:
Birth Date:
Email Address:
Phone Number():
Address():
Comments:

Drug and Alcohol Testing. The following people have been determined by the Coast Guard, Law Enforcement Personnel, and/or the Marine Employer to have been directly involved in a Serious Marine Incident as defined in 46 CFR 4.03-2:

Response Resources. The following incident response resources were subjects of this investigation.

Resource Name: RBS - 25406

Resource ID: 25406 Kind: Vessels

Sub-Kind: SAR/Law Enforcement Vessel

Type:

Resource Name: RBS - 25501

Resource ID: 25501 Kind: Vessels

Sub-Kind: SAR/Law Enforcement Vessel

Type:

Resource Name: UTB - 41392

Resource ID: 41392 Kind: Vessels

Sub-Kind: SAR/Law Enforcement Vessel

Type:

Resource Name: UTB - 41392

Resource ID: 41392 Kind: Vessels

Sub-Kind: SAR/Law Enforcement Vessel

Type:

Other Subjects. The following were subjects of this investigation.

Waterway Segment(s). The following waterway segment(s) were subjects of this investigation.

Incident Information

Location(s).

DescriptionLatitudeLongitudeIncident Location37 46.0 N122 18.0 W

Sequence of Events.

11/07/2007 16:30:00 to 11/07/2007 16:30:00 (Estimated): Initial Notification - SF BAR PILOT UNIT 9 WAS PILOTING THE M/V COSCO BUSAN UNDER THE OAKLAND BAY BRIDGE AND STUCK THE DELTA TOWER OF THE BRIDGE.

Action Type: Other Actions - Reporting/Notifications
Action Class: Report/Notification of Casualty or Incident

Location: Known; US Waters

Description: Incident Location

Latitude: 37 46.0 N Longitude: 122 18.0 W

Subject(s) and Details:

Name Type Status Role
Cota, John Party Not at Risk Other

Details Filed: Notification Incident Detail/Location

Incident Type: MS: Allision

Incident Date/Time: 11/07/2007 4:30:00 PM

Notification Method: VHF/FM (other than Channel 16)

Date/Time Notified: 11/07/2007 4:30:00 PM

Specific Notification Problem: No

Incident Location:

Address:

City, St, Zip: Province/Country:

Latitude: 37 46.0 N Longitude: 122 18.0 W

General Location/Affected Area

Reporting Party

Name: John Cota

Callback Phone: Cell Phone:

Location:

Address: City, ST, Zip: Province/Country:

Facility Name: Organization:

Latitude: 0 Longitude: 0

General Location:

Involved Subjects

Incident Description

SF BAR PILOT UNIT 9 WAS PILOTING THE M/V COSCO BUSAN UNDER THE OAKLAND BAY BRIDGE AND STUCK THE DELTA TOWER OF THE BRIDGE.

V. CAUSAL ANALYSIS

The Initiating Event of the Incident

Initiating Event:

Failures of Defense Against Subsequent Events in the Incident

VI. REFERRAL FOR ENFORCEMENT ACTION

The following referrals for enforcement action have been made as a result of this investigation and represent those instances where the Coast Guard has gathered evidence that indicates one or more alleged violations or offenses may have occurred. Any determinations as to whether or not one or more actual violations or offenses have occurred are documented in the appropriate Coast Guard enforcement activities.

APPENDIX 1 - EVIDENCE

3095030 001 DF

Pilot card (1).pdf

Collection Information:

Date/Time: 11/10/2007 2:56:00 PM

Location: Sector SF

Collected By: USCG Gathered; I/O Div, SEC SanFran

Witnessed By: USCG Witness;,

Tracking: Attachments:

- Pilot card (1).pdf; Sector San Francisco; Fernandez, David .; 11/10/2007;

3095030 002 DF

Log entries (2).pdf

Collection Information:

Date/Time: 11/10/2007 3:01:00 PM

Location: Sec SF

Collected By: USCG Gathered; IO Div, SEC SanFran

Witnessed By: USCG Witness;,

Tracking: Attachments:

- Log entries (2).pdf; Sector San Francisco; Fernandez, David .; 11/10/2007;

3095030 003 DF

Bridge log (3).pdf

Collection Information:

Date/Time: 11/10/2007 3:03:00 PM

Location: Sec SF

Collected By: USCG Gathered; IO Div, SEC SanFran

Witnessed By: USCG Witness;,

Tracking:

Attachments:

- Bridge log (3).pdf; Sector San Francisco; Fernandez, David .; 11/10/2007;

3095030 004 DF

Bell log (4).pdf

Collection Information:

Date/Time: 11/10/2007 3:04:00 PM

Location: Sec SF

Collected By: USCG Gathered; IO Div, SEC SanFran

Witnessed By: USCG Witness;,

Tracking:

Attachments:

- Bell log (4).pdf; Sector San Francisco; Fernandez, David .; 11/10/2007;

3095030 005 DF

Vessel Heading Printout (5).pdf

Collection Information:

Date/Time: 11/10/2007 3:05:00 PM

Location: Sec SF

Collected By: USCG Gathered; IO Div, SEC SanFran

Witnessed By: USCG Witness;,

Tracking: Attachments:

- Vessel Heading Printout (5).pdf; Sector San Francisco; Fernandez, David .; 11/10/2007;

3095030 006 DF

Vessel Bridge Team Instruction (6).pdf

Collection Information:

Date/Time: 11/10/2007 3:06:00 PM

Location: Sec SF

Collected By: USCG Gathered; IO Div, SEC SanFran

Witnessed By: USCG Witness;,

Tracking: Attachments:

Vessel Bridge Team Instruction (6).pdf; Sector San Francisco; Fernandez, David
 .; 11/10/2007;

3095030 007 DF

Vessel Response Plan (7).pdf

Collection Information:

Date/Time: 11/10/2007 3:07:00 PM

Location: Sec SF

Collected By: USCG Gathered; IO Div, SEC SanFran

Witnessed By: USCG Witness;,

Tracking: Attachments:

- Vessel Response Plan (7).pdf; Sector San Francisco; Fernandez, David .; 11/10/2007;

3095030 008 DF

Crew List (8).pdf

Collection Information:

Date/Time: 11/10/2007 3:09:00 PM

Location: Sec SF

Collected By: USCG Gathered; IO Div, SEC SanFran

Witnessed By: USCG Witness;,

Tracking: Attachments:

- Crew List (8).pdf; Sector San Francisco; Fernandez, David .; 11/10/2007;

3095030 009 DF

Spilled Quantity Cals and Tank Sounding (9).pdf

Collection Information:

Date/Time: 11/10/2007 3:11:00 PM

Location: Sec SF

Collected By: USCG Gathered; IO Div, SEC SanFran

Witnessed By: USCG Witness;,

Tracking: Attachments:

- Spilled Quantity Cals and Tank Sounding (9).pdf; Sector San Francisco; Fernandez, David .; 11/10/2007;

3095030 010 DF

Captain statement (10).pdf Collection Information:

Date/Time: 11/10/2007 3:12:00 PM

Location: Sec SF

Collected By: USCG Gathered; IO Div, SEC SanFran

Witnessed By: USCG Witness;,

Tracking: Attachments:

- Captain statement (10).pdf; Sector San Francisco; Fernandez, David .; 11/10/2007;

3095030 011 DF

Third mate statement (11).pdf

Collection Information:

Date/Time: 11/10/2007 3:13:00 PM

Location: Sec SF

Collected By: USCG Gathered; IO Div, SEC SanFran

Witnessed By: USCG Witness;,

Tracking: Attachments:

- Third mate statement (11).pdf; Sector San Francisco; Fernandez, David .; 11/10/2007;

3095030 012 DF

Helmsman statement (12).pdf

Collection Information:

Date/Time: 11/10/2007 3:14:00 PM

Location: Sec SF

Collected By: USCG Gathered; IO Div, SEC SanFran

Witnessed By: USCG Witness;,

Tracking: Attachments:

- Helmsman statement (12).pdf; Sector San Francisco; Fernandez, David .;

11/10/2007;

3095030 013 DF

Pilot statement (13).pdf Collection Information:

Date/Time: 11/10/2007 3:18:00 PM

Location: Sec SF

Collected By: USCG Gathered; IO Div, SEC SanFran

Witnessed By: USCG Witness;,

Tracking: Attachments:

- Pilot statement (13).pdf; Sector San Francisco; Fernandez, David .; 11/10/2007;

3095030 014 DF

Master's_Mao Cai Sun_ COC Urine(14).pdf

Collection Information:

Date/Time: 11/10/2007 3:21:00 PM

Location: Sec SF

Collected By: USCG Gathered; IO Div, SEC SanFran

Witnessed By: USCG Witness;,

Tracking:

Attachments:

- COC Urine Master Mao Cai Sun (14).pdf; Sector San Francisco; Fernandez,

David .; 11/10/2007;

3095030 015 DF

Pilot alcohol and drug tests (15).pdf

Collection Information:

Date/Time: 11/10/2007 3:33:00 PM

Location: Sec SF

Collected By: USCG Gathered; IO Div, SEC SanFran

Witnessed By: USCG Witness;,

Tracking: Attachments:

- Pilot alcohol and drug tests (15).pdf; Sector San Francisco; Fernandez, David .;

11/10/2007;

3095030 016 DF

3rd Mate Hong Zhi Wang Chain of Custody for Urine sample (16).pdf

Collection Information:

Date/Time: 11/10/2007 3:35:00 PM

Location: Sec SF

Collected By: USCG Gathered; IO Div, SEC SanFran

Witnessed By: USCG Witness;,

Tracking:

Attachments:

- COC Urine 3rd Mate Hong Zhi Wang (16).pdf; Sector San Francisco;

Fernandez, David .; 11/10/2007;

3095030 017 DF

Helmsman Zong Bin Li Chain of Custody for Urine sample (17).pdf

Collection Information:

Date/Time: 11/10/2007 3:36:00 PM

Location: Sec SF

Collected By: USCG Gathered; IO Div, SEC SanFran

Witnessed By: USCG Witness;,

Tracking:

Attachments:

- COC Urine Helmsman Zong Bin Li (17).pdf; Sector San Francisco; Fernandez, David .; 11/10/2007;

3095030 018 DF

Chief Engineer Ying Quan Yao Chain of Custody for Urine sample (18).pdf

Collection Information:

Date/Time: 11/10/2007 3:37:00 PM

Location: Sec SF

Collected By: USCG Gathered; IO Div, SEC SanFran

Witnessed By: USCG Witness;,

Tracking:

Attachments:

- COC Urine Chief Engineer Ying Quan Yao (18).pdf; Sector San Francisco; Fernandez, David .; 11/10/2007;

3095030 019 DF

BSN_Liang Xian Zheng_Chain of Custody for Urine sample (19).pdf

Collection Information:

Date/Time: 11/10/2007 3:38:00 PM

Location: Sec SF

Collected By: USCG Gathered; IO Div, SEC SanFran

Witnessed By: USCG Witness;,

Tracking:

Attachments:

- COC Urine BSN Liang Xian Zheng (19).pdf; Sector San Francisco; Fernandez, David .; 11/10/2007;

3095030 020 DF

2E_Ying Quan Shen_ Chain of Custody for Urine sample (20).pdf

Collection Information:

Date/Time: 11/10/2007 3:43:00 PM

Location: Sec SF

Collected By: USCG Gathered; IO Div, SEC SanFran

Witnessed By: USCG Witness;,

Tracking:

Attachments:

- COC Urine 2E Ying Quan Shen (20).pdf; Sector San Francisco; Fernandez, David .; 11/10/2007;

3095030 021 DF

CO_Kong Xiang Hu_ Chain of Custody for Urine sample (21).pdf

Collection Information:

Date/Time: 11/10/2007 3:49:00 PM

Location: Sec SF

Collected By: USCG Gathered; IO Div, SEC SanFran

Witnessed By: USCG Witness;,

Tracking:

Attachments:

- CO_Kong Xiang Hu_ Chain of COC Urine (21).pdf; Sector San Francisco; Fernandez, David .; 11/10/2007;

3095030 022 DF

Delta tower 1(22a&b).JPG

Collection Information:

Date/Time: 11/10/2007 3:53:00 PM

Location: Sec SF

Collected By: USCG Gathered; IO Div, SEC SanFran

Witnessed By: USCG Witness;,

Tracking:

Attachments:

- Delta tower 1(22a). JPG; Sector San Francisco; Fernandez, David .; 11/10/2007;
- Delta Tower 2 (22b).JPG; Sector San Francisco; Fernandez, David .; 11/10/2007;

3095030 023 DF

Ship Photos (4 files)

Collection Information:

Date/Time: 11/10/2007 3:55:00 PM

Location: Sec SF

Collected By: USCG Gathered; IO Div, SEC SanFran

Witnessed By: USCG Witness;,

Tracking:

Attachments:

- Close up shot of COSCO BUSAN 6 (23a).JPG; Sector San Francisco;

Fernandez, David .; 11/10/2007;

- COSCO BUSAN 3(23b).JPG; Sector San Francisco; Fernandez, David .; 11/10/2007;
- COSCO BUSAN 4 (23c). JPG; Sector San Francisco; Fernandez, David .; 11/10/2007;
- COSCO BUSAN 5 (23d).JPG; Sector San Francisco; Fernandez, David .; 11/10/2007;

3095030 024 DF

Ship Charts (6 files)

Collection Information:

Date/Time: 11/10/2007 3:57:00 PM

Location: Sec SF

Collected By: USCG Gathered; IO Div, SEC SanFran

Witnessed By: USCG Witness;

Tracking:

Attachments:

- DSC01127 (24a). JPG; Sector San Francisco; Fernandez, David .; 11/10/2007;
- DSC01128 (24b).JPG; Sector San Francisco; Fernandez, David .; 11/10/2007;
- DSC01129 (24c), JPG: Sector San Francisco; Fernandez, David .: 11/10/2007;
- DSC01135 (24d).JPG; Sector San Francisco; Fernandez, David .; 11/10/2007;
- DSC01137 (24e). JPG; Sector San Francisco; Fernandez, David .; 11/10/2007;

- DSC01142 (24f).JPG; Sector San Francisco; Fernandez, David .; 11/10/2007;

3095030 025 DF

VTS Screen Shots (4 files)

Collection Information:

Date/Time: 11/10/2007 4:04:00 PM

Location: Sec SF

Collected By: USCG Gathered; IO Div, SEC SanFran

Witnessed By: USCG Witness;,

Tracking:

Attachments:

- 11 07 2007 08 32 34 Track History (25a).bmp; Sector San Francisco; Fernandez, David .: 11/10/2007;
- Time Mr Shepherd Intentionl (25b).bmp; Sector San Francisco; Fernandez, David .; 11/10/2007;
- Allision (25c).bmp; Sector San Francisco; Fernandez, David .; 11/10/2007;
- Report of Allision from Cosco Busan(25d).bmp; Sector San Francisco; Fernandez, David .; 11/10/2007;

3095030 026 DF

Radio Communication with VTS (3 .wav files)

Collection Information:

Date/Time: 11/10/2007 4:13:00 PM

Location: Sec SF

Collected By: USCG Gathered; IO Div, SEC SanFran

Witnessed By: USCG Witness;,

Tracking:

Attachments:

- Shepard Verify Intentions.wav; Sector San Francisco; Fernandez, David .; 11/10/2007;
- Report of Bridge Allision.wav; Sector San Francisco; Fernandez, David .; 11/10/2007;
- Phone Conversations.wav; Sector San Francisco; Fernandez, David .; 11/10/2007;

3095030 027 DF

IO_CWO_Reavis_Interview Summary of Pilot(27).pdf

Collection Information:

Date/Time: 11/10/2007 4:15:00 PM

Location:

Collected By: USCG Gathered;, Witnessed By: USCG Witness;,

Tracking:

Attachments:

- IO_CWO_Reavis_Interview Summary of Pilot(27).pdf; Sector San Francisco; Fernandez, David .; 11/10/2007;

3095030 028 DF

IO LTJG Rosario Interview Summary of Pilot (28).pdf

Collection Information:

Date/Time: 11/10/2007 4:35:00 PM

Location: Sec SF

Collected By: USCG Gathered; IO Div, SEC SanFran

Witnessed By: USCG Witness;,

Tracking: Attachments:

- IO_LTJG Rosario_Interview Summ of Pilot(28).pdf; Sector San Francisco; Fernandez, David .; 11/10/2007;

3095030 029 DF

IO_CWO_Reavis_Interview Summary of Master(29).pdf

Collection Information:

Date/Time: 11/10/2007 4:36:00 PM

Location: Sec SF

Collected By: USCG Gathered; IO Div, SEC SanFran

Witnessed By: USCG Witness;,

Tracking: Attachments:

- IO_CWO_Reavis_Interview Summary with Master(29).pdf; Sector San Francisco; Fernandez, David .; 11/10/2007;

3095030 030 DF

IO_CWO_Reavis_Interview Summary of A/B Helmsman(30).pdf

Collection Information:

Date/Time: 11/10/2007 4:37:00 PM

Location: Sec SF

Collected By: USCG Gathered; IO Div, SEC SanFran

Witnessed By: USCG Witness;,

Tracking: Attachments:

- IO_CWO_Reavis_Interview Summary of Helmsan(30).pdf; Sector San Francisco; Fernandez, David .; 11/10/2007;

3095030 031 DF

IO_CWO_Reavis_Interview Summary of 3rd Mate(31).pdf

Collection Information:

Date/Time: 11/10/2007 4:38:00 PM

Location: Sec SF

Collected By: USCG Gathered; IO Div, SEC SanFran

Witnessed By: USCG Witness;,

Tracking: Attachments:

- IO_CWO_Reavis_Interview Summary with 3rd Mate (31).pdf; Sector San Francisco; Fernandez, David .; 11/10/2007;

3095030 032 DF

IO_LTJG_Rosario_Interview Summary of 3rd Mate (32).pdf Collection Information:

Date/Time: 11/10/2007 4:39:00 PM

Location: Sec SF

Collected By: USCG Gathered; IO Div, SEC SanFran

Witnessed By: USCG Witness;,

Tracking: Attachments:

- IO_LTJG Rosario_Interview Summ of 3rdMate(32).pdf; Sector San Francisco; Fernandez, David .; 11/10/2007;

3095030 033 DF

IO_LTJG_Rosario_Interview Summary of Master (33).pdf

Collection Information:

Date/Time: 11/10/2007 4:40:00 PM

Location: Sec SF

Collected By: USCG Gathered; IO Div, SEC SanFran

Witnessed By: USCG Witness;,

Tracking: Attachments:

- IO_LTJG Rosario_Interview Summ of Master(33).pdf; Sector San Francisco; Fernandez, David .; 11/10/2007;

3095030 034 DF

Statement VTS Supervisor Mark J Perez (34).pdf

Collection Information:

Date/Time: 11/10/2007 4:56:00 PM

Location: Sec SF

Collected By: USCG Gathered; IO Div, SEC SanFran

Witnessed By: USCG Witness;

Tracking: Attachments:

- M Perez VTS Sup (34).pdf; Sector San Francisco; Fernandez, David .; 11/10/2007;

3095030 035 DF

Statement VTS Specialist Franklin H. Shepherd (35).pdf

Collection Information:

Date/Time: 11/10/2007 4:58:00 PM

Location: Sec SF

Collected By: USCG Gathered; IO Div, SEC SanFran

Witnessed By: USCG Witness;,

Tracking:

Attachments:

- Mr Shepherd VTS Spe(35).pdf; Sector San Francisco; Fernandez, David .; 11/10/2007;

3095030 036 DF

Statement VTS Ops Specialist Drew P. Cooper(36).pdf

Collection Information:

Date/Time: 11/10/2007 5:00:00 PM

Location: Sec SF

Collected By: USCG Gathered; IO Div, SEC SanFran

Witnessed By: USCG Witness;,

Tracking: Attachments:

- FW Statement from P O Cooper(36).msg; Sector San Francisco; Fernandez, David .; 11/10/2007;

3095030-MISLE-001

MISLE Notification #280496 for report of incident received by VHF/FM (other than Channel 16).

Collection Information:

Date/Time: 11/07/2007 4:30:00 PM Location: Sector San Francisco

Collected By: USCG Gathered; Rosario, Nephtwim., Sector San Francisco

Witnessed By: USCG Witness;,

Tracking: Attachments:

APPENDIX 2 - CORRESPONDENCE

Sequence of Events.

11/07/2007 17:04:00 (Known): Response Resource Requested

Action Class: Resource Action

Sub-Type: Resource Ordered/Requested

Location:

Subject(s) and Details:

Name Type Status Role

UTB - 41392 Resource

Details Filed: None

11/07/2007 17:04:00 (Known): UTB - 41392 USCG - CG STA SAN FRANCISCO Launched

Action Class: Resource Action

Sub-Type: Resource Dispatched/Launched

Location:

Subject(s) and Details:

<u>Name</u> <u>Type</u> <u>Status</u> <u>Role</u>

UTB - 41392 Resource

Details Filed: None

11/07/2007 17:13:00 (Known): UTB - 41392 USCG - CG STA SAN FRANCISCO On Scene at 071713Z NOV 07

Action Class: Resource Action
Sub-Type: Resource On-scene

Location:

Subject(s) and Details:

Name Type Status Role

UTB - 41392 Resource

Details Filed: None

11/07/2007 17:13:00 (Known): Target Located at 071713Z NOV 07

Event Class: Target Located

Sub-Type: Location:

Subject(s) and Details:

Name Type Status Role

UTB - 41392 Resource

11/07/2007 17:13:00 (Known): UTB - 41392 USCG - CG STA SAN FRANCISCO Alongside

Action Class: Resource Action

Sub-Type: Resource Alongside/Overhead

Location:

Subject(s) and Details:

Name <u>Type</u> <u>Status</u> <u>Role</u>

UTB - 41392 Resource

Details Filed: None

11/07/2007 20:07:00 (Known): UTB - 41392 USCG - CG STA SAN FRANCISCO Departed Scene

Action Class: Resource Action

Sub-Type: Resource Depart Scene

Location:

Subject(s) and Details:

Name Type Status Role

UTB - 41392 Resource

Details Filed: None

11/07/2007 20:10:00 (Known): UTB - 41392 USCG - CG STA SAN FRANCISCO Sortie Ended

Action Class: Resource Action Sub-Type: Resource RTB

Location:

Subject(s) and Details:

Name Type Status Role

UTB - 41392 Resource

Sequence of Events.

11/07/2007 18:17:00 (Known): Response Resource Requested

Action Class: Resource Action

Sub-Type: Resource Ordered/Requested

Location:

Subject(s) and Details:

Name Type Status Role

RBS - 25501 Resource

Details Filed: None

11/07/2007 18:17:00 (Known): RBS - 25501 USCG - CG STA SAN FRANCISCO Launched

Action Class: Resource Action

Sub-Type: Resource Dispatched/Launched

Location:

Subject(s) and Details:

<u>Name</u> <u>Type</u> <u>Status</u> <u>Role</u>

RBS - 25501 Resource

Details Filed: None

11/07/2007 18:25:00 (Known): RBS - 25501 USCG - CG STA SAN FRANCISCO On Scene at 071825Z NOV 07

Action Class: Resource Action
Sub-Type: Resource On-scene

Location:

Subject(s) and Details:

Name Type Status Role

RBS - 25501 Resource

Details Filed: None

11/07/2007 18:25:00 (Known): Target Located at 071825Z NOV 07

Event Class: Target Located

Sub-Type: Location:

Subject(s) and Details:

Name Type Status Role

RBS - 25501 Resource

11/07/2007 18:25:00 (Known): RBS - 25501 USCG - CG STA SAN FRANCISCO Alongside

Action Class: Resource Action

Sub-Type: Resource Alongside/Overhead

Location:

Subject(s) and Details:

Name Type Status Role

RBS - 25501 Resource

Details Filed: None

11/07/2007 22:04:00 (Known): RBS - 25501 USCG - CG STA SAN FRANCISCO Departed Scene

Action Class: Resource Action

Sub-Type: Resource Depart Scene

Location:

Subject(s) and Details:

Name Type Status Role

RBS - 25501 Resource

Details Filed: None

11/08/2007 22:14:00 (Known): RBS - 25501 USCG - CG STA SAN FRANCISCO Sortie Ended

Action Class: Resource Action Sub-Type: Resource RTB

Location:

Subject(s) and Details:

Name Type Status Role

RBS - 25501 Resource

Sequence of Events.

11/07/2007 21:10:00 (Known): Response Resource Requested

Action Class: Resource Action

Sub-Type: Resource Ordered/Requested

Location:

Subject(s) and Details:

<u>Name</u> <u>Type</u> <u>Status</u> <u>Role</u>

RBS - 25406 Resource

Details Filed: None

11/07/2007 21:10:00 (Known): RBS - 25406 USCG - CG STA SAN FRANCISCO Launched

Action Class: Resource Action

Sub-Type: Resource Dispatched/Launched

Location:

Subject(s) and Details:

<u>Name</u> <u>Type</u> <u>Status</u> <u>Role</u>

RBS - 25406 Resource

Details Filed: None

11/07/2007 21:20:00 (Known): RBS - 25406 USCG - CG STA SAN FRANCISCO On Scene at 072120Z NOV 07

Action Class: Resource Action
Sub-Type: Resource On-scene

Location:

Subject(s) and Details:

Name Type Status Role

RBS - 25406 Resource

Details Filed: None

11/07/2007 21:20:00 (Known): Target Located at 072120Z NOV 07

Event Class: Target Located

Sub-Type: Location:

Subject(s) and Details:

Name Type Status Role

RBS - 25406 Resource

11/07/2007 21:20:00 (Known): RBS - 25406 USCG - CG STA SAN FRANCISCO Alongside

Action Class: Resource Action

Sub-Type: Resource Alongside/Overhead

Location:

Subject(s) and Details:

Name Type Status Role

RBS - 25406 Resource

Details Filed: None

 $11/07/2007\ 21:30:00$ (Known): RBS - $25406\ USCG$ - CG STA SAN FRANCISCO Departed Scene

Action Class: Resource Action

Sub-Type: Resource Depart Scene

Location:

Subject(s) and Details:

Name Type Status Role

RBS - 25406 Resource

Details Filed: None

11/07/2007 21:38:00 (Known): RBS - 25406 USCG - CG STA SAN FRANCISCO Sortie Ended

Action Class: Resource Action Sub-Type: Resource RTB

Location:

Subject(s) and Details:

Name Type Status Role

RBS - 25406 Resource

Sequence of Events.

11/07/2007 22:41:00 (Known): Response Resource Requested

Action Class: Resource Action

Sub-Type: Resource Ordered/Requested

Location:

Subject(s) and Details:

<u>Name</u> <u>Type</u> <u>Status</u> <u>Role</u>

UTB - 41392 Resource

Details Filed: None

11/07/2007 22:41:00 (Known): UTB - 41392 USCG - CG STA SAN FRANCISCO Launched

Action Class: Resource Action

Sub-Type: Resource Dispatched/Launched

Location:

Subject(s) and Details:

<u>Name</u> <u>Type</u> <u>Status</u> <u>Role</u>

UTB - 41392 Resource

Details Filed: None

11/07/2007 23:33:00 (Known): UTB - 41392 USCG - CG STA SAN FRANCISCO On Scene at 072333Z NOV 07

Action Class: Resource Action
Sub-Type: Resource On-scene

Location:

Subject(s) and Details:

Name Type Status Role

UTB - 41392 Resource

Details Filed: None

11/08/2007 1:21:00 (Known): UTB - 41392 USCG - CG STA SAN FRANCISCO Sortie Ended

Action Class: Resource Action Sub-Type: Resource RTB

Location:

Subject(s) and Details:

Name Type Status Role

UTB - 41392 Resource



Activity Summary Report

Title: ISM Exam Activity ID: 3095968

Activity Start Time: 11/09/2007 11:16:00 AM

Originating Unit: SEC SanFran Owner Unit: SEC SanFran Controlling Unit: SEC SanFran

Activity Type: Vessel Inspection/PSC Team Lead: Johnson, Bryan D. Status: Open - In Progress

Status Date: 11/09/2007 Prompt Date:

Subject POC:

LT Hsing-Yen Fu **Operating Organization Name**

REGAL Stone LTD Corporation

Address City State Zip Country **Province** Rm 1603, 16th Floor, MassMutual Tower38 Gloucester Rd Wanchai HK

Vessel Information

Vessel Name: VIN: Lenath: COSCO BUSAN 9231743 901.2

Year Completed: **Vessel Type: Propulsion**

Type:

General Dry Cargo Ship-Container Ship-General 2001 Diesel Direct

Engine Compartment: Fuel Compartment: Construction: Unknown Unknown Unknown

Activities Conducted:

Type Date Unit

SEC SanFran ISM Exam 11/09/07

Operational Controls:

Control Type Reason **Initiated Jurisdiction** IMO Related Detention Vessel Movement, Other 11/09/07 US Coast Guard

Restriction Description

Vessel Movement Limitation Vessel is detained in the Port of San Francisco Bay until the deficiencies are addressed to the satisfaction of the attending Coast Guard marine inspector and the vessel"s classification society.

Inspection Results

System Date Results

Operations/Management 11/09/07 **Outstanding Deficiencies Exist**

Inspection Results - Deficiencies

ITEM COMPLIANCE DATE DATE ISSUED **DATE RESOLVED**

11/09/2007

SYSTEM

SUBSYSTEM

COMPONENT

Navigation Underway, General

Operations/Management **Navigation Safety** ---Description---

Based on an allision of the vessel with the San Francisco Bay Bridge on 07 November 2007 and statements made by the vessel's Master and crew describing conditions and operations on the bridge before and during the transit, the crew is not operating in accordance with the vessel's Bridge Procedures Manual and Safety Management System.

Documents and Certificates:		
(none)		

Locations: Latitude

Longitude ------

Time

Description

37 48.6444 N

122 22.074 W

11/09/2007 11:16

Anchorage 9

Narrative Summary:

07NOV07: PSC inspectors boarded the vessel along with IO's for post-casualty investigation of vessel. During the course of the investigation, PSC inspectors noticed possible lapses in the implementation of the Bridge Safety Management System. Conducted expanded ISM exam regarding Bridge Management. Inspectors found, through the exam and interviews with vessel crew, that the bridge was likely not manned commiserate with the environmental conditions at the time of the casualty. Also, they noticed that the fixes were not plotted as often as required. According to the 3/O who was on the bridge at the time, he was unable to comply with requirements b/c he was manning the EOT at the same time. Vessel detained for failure to implement the ISM. Form B requested ISM audit to be completed.

Activity Action Log:

Eff. Date Unit Individual

Description

SEC SanFran 11/09/2007 In Progress"

Johnson, Bryan D.

Activity Created. Status: "Open -

Cargo Transfer Statistics:

Case Title: MS Allision/ 37 46. N 122 18. W/071630ZNOV07

Case Number: 381733 Activity Number: 3096205

Date/TimeSubject(s)Entered By071630ZNOV07<no subject>Cooper, Drew P.

Message

Initial Notification - SF BAR PILOT UNIT R WAS PILOTING THE M/V COSCO BUSAN UNDER THE OAKLAND BAY BRIDGE AND STUCK THE DELTA TOWER OF THE BRIDGE.

Date/Time Subject(s) Entered By
071630ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

SCC rovd rpt from VTS stating that the M/V Cosco Busan had struck the delta tower of the bay bridge while transiting outbound from Oakland. The vsl is now at anchorage 7. VTS reports they will contact CALTRANS

Date/TimeSubject(s)Entered By071631ZNOV07COSCO BUSAN; COTA, JOHNFlesher, Gabriel

Message

Date/Time Subject(s) Entered By
071633ZNOV07 <no subject> Cooper, Drew P.

Message

SEC SF VTS BRIEFED CAL TRANS: ALLISION TO THE EAST SIDE OF THE DELTA TOWER OF THE OAKLAND BAY BRIDGE. REPORTED DAMAGE TO PILEINGS.

Date/Time Subject(s) Entered By
071636ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

SCC issued an SMIB about the COSCO BUSAN making contact with the Bay Bridge. SMIB warned all vsls to keep a 100yrd distance from the vsl and to transit the area with caution. SMIB is to be issued every 15 minutes.

Date/Time Subject(s) Entered By
071637ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

SU briefed ENS Hopper

Date/Time Subject(s) Entered By
071640ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

SCC briefed Mr. Sulouff at D11

Date/TimeSubject(s)Entered By071646ZNOV07<no subject>NAGLE, RUSSELL P.

Message

Briefed STA SF for launch to investigate damage to bridge and vessel

Date/Time Subject(s) Entered By
071648ZNOV07 <no subject> Cooper, Drew P.

Message

PIER DEBRIS AND FUEL IN WATER DID NOT KNOW THE FULL EXTENT OF DAMAGE. RECOMMENDED CONTACT ARMY CORP OF ENGINEERS AND RESPOND TO DEBRIS IN WATER.

Date/TimeSubject(s)Entered By071650ZNOV07COSCO BUSANCooper, Drew P.

Message

COSCO BUSAN RPTD TO VTS: ANCHORED IN ANCHORAGE 7.

Date/Time Subject(s) Entered By

071650ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

Briefed IMD, MST2 Anderson will be departing to investigate spill

Date/Time Subject(s) Entered By

071650ZNOV07 <no subject> bidowski, andrea .

Message

SCC was notified by NRC (report # 853865) that there was oil in the water caused by the M/V Cosco Busan. IMD was briefed via phone.

Date/Time Subject(s) Entered By 071655ZNOV07 COTA, JOHN; HOBURG, ELLSWORTH F Cooper, Drew P.

Message

MR HOBURG (SF BARY PILOT UNIT: 37) STATED HE HAD RELIEVED CAPTAIN JOHN COTA (SF BAR PILOT UNIT: R).

Date/Time Subject(s) Entered By
071659ZNOV07 <no subject> Cooper, Drew P.

Message

VTS SF SENT SECURITE BCST TO INFORM VESSELS OF MINIMUM WAKE AROUND COSCO BUSAN IN ANC 7.

 Date/Time
 Subject(s)
 Entered By

 071704ZNOV07
 UTB - 41392
 Boyd, Ryan E.

Message

Response Resource Requested

Date/Time Subject(s) Entered By 071704ZNOV07 UTB - 41392 Boyd, Ryan E.

Message

UTB - 41392 USCG - CG STA SAN FRANCISCO Launched

Date/Time Subject(s) Entered By 071705ZNOV07 <no subject> Cooper, Drew P.

Message

VTS SF NTFD THE ACOE OF THE DEBRIS IN THE WATER SOUTH OF THE OAKLAND BAY BRIDGE.

Date/TimeSubject(s)Entered By071710ZNOV07LYNN MARIECooper, Drew P.

Message

TUB LYNN MARIE INFORMED VTS THAT THE TUG HAD SPOTTED FUEL AND DEBRIS FROM YERBA BUENA ISLAND TO THE ALPHA TOWER OF THE OAKLAND BAY BRIDGE.

Date/Time Subject(s) Entered By 071713ZNOV07 UTB - 41392 Boyd, Ryan E.

Message

UTB - 41392 USCG - CG STA SAN FRANCISCO On Scene at 071713Z NOV 07

Date/Time Subject(s) Entered By 071713ZNOV07 UTB - 41392 Boyd, Ryan E.

Message

Target Located at 071713Z NOV 07

Date/Time Subject(s) Entered By 071713ZNOV07 UTB - 41392 Boyd, Ryan E.

Message

UTB - 41392 USCG - CG STA SAN FRANCISCO Alongside

Date/Time Subject(s) Entered By 071722ZNOV07 <no subject> Cooper, Drew P.

Message

ACOE STATED THAT THEY WOULD SEND ASSESTS TO ASSIST IN DEBRIS CLEAN UP.

Date/Time Subject(s) Entered By

071722ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

contacted agent who stated that OSRO had been notified

Date/Time Subject(s) Entered By 071723ZNOV07 HOBURG, ELLSWORTH F Cooper, Drew P.

Message

INQUIRED IF ANY OF THE OIL RESPONSE BOATS HAVE CHECKED IN FOR THE COSCO BUSAN. NO OIL RESPONSE VESSELS HAVE CHECKED IN AS OF YET. VTS QUERRIED THE PILOT ON FUEL LEAKAGE SITUATION. PILOT'S RESPONSE WAS THE SHIP'S CREW HAS SECURED THE FUEL SPILL.

Date/TimeSubject(s)Entered By071730ZNOV07<no subject>NAGLE, RUSSELL P.

Message

conducted virtual brief

Date/Time Subject(s) Entered By
071739ZNOV07 <no subject> Cooper, Drew P.

Message

CAL TRANS RPTD TO VTS THAT INVESTIGATORS WERE ON SEEN TO CHECK THE STURCTURAL DAMGAE TO THE TOWER.

Date/Time Subject(s) Entered By
071745ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

SCC initiated CIC; CIC request denied due to the issue being a local issue.

Date/Time Subject(s) Entered By
071745ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

PO Anderson reports the sounding tube appears bent; resulting in uncertain information regarding fuel discharge.

Date/Time Subject(s) Entered By 071754ZNOV07 HOBURG, ELLSWORTH F Cooper, Drew P.

Message

REQUESTED TO SHIFT THE VESSEL TO ANCHORAGE 9 DUE TO DRAFT CONCERNS, THE VESSEL IS DRAWING 40'4" ANCHORAGE 7 IS NOT AN IDEAL ANCHORAGE FOR THE VESSEL. SEC SF SMC AUTHORIZED.

Date/Time Subject(s) Entered By
071754ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

COSCO BUSAN enr Anchoarage 9

Date/Time Subject(s) Entered By
071757ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

CGC Tern briefed for launch

Date/Time Subject(s) Entered By 071758ZNOV07 COSCO BUSAN Cooper, Drew P.

Message

SEC SF VTS NOTIFIED VSL THAT VESSEL HAD TO MAINTAIN ATLEAST 1 NM DISTANCE FROM ANY ANCHORED VESSEL.

Date/TimeSubject(s)Entered By071807ZNOV07COSCO BUSAN; HOBURG, ELLSWORTH FCooper, Drew P.

Message

UNIT 37 ONBOARD THE COSCO BUSAN CONTACTED SEC SF VTS PREPARING TO DEPART ANCHORAGE 7 FOR ANCHORAGE 9.

Date/Time Subject(s) Entered By 071812ZNOV07 <no subject> bidowski, andrea .

Message

We received a call from Danny Herod at O'Briens stating that an OSRO Team is getting assembled.

 Date/Time
 Subject(s)
 Entered By

 071817ZNOV07
 RBS - 25501
 Boyd, Ryan E.

Message

Response Resource Requested

Date/Time Subject(s) Entered By 071817ZNOV07 RBS - 25501 Boyd, Ryan E.

Message

RBS - 25501 USCG - CG STA SAN FRANCISCO Launched

Date/Time Subject(s) Entered By 071822ZNOV07 <no subject> Cooper, Drew P.

Message

NOTIFIED THAT M/V COSCO BUSAN UNDERWAY FOR ANCHORAGE 9

Date/Time Subject(s) Entered By
071822ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

CGC Tern assumes PATCOM

 Date/Time
 Subject(s)
 Entered By

 071825ZNOV07
 RBS - 25501
 Boyd, Ryan E.

Message

RBS - 25501 USCG - CG STA SAN FRANCISCO On Scene at 071825Z NOV 07

 Date/Time
 Subject(s)
 Entered By

 071825ZNOV07
 RBS - 25501
 Boyd, Ryan E.

Message

Target Located at 071825Z NOV 07

 Date/Time
 Subject(s)
 Entered By

 071825ZNOV07
 RBS - 25501
 Boyd, Ryan E.

Message

RBS - 25501 USCG - CG STA SAN FRANCISCO Alongside

Date/Time Subject(s) Entered By
071830ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

The O'Brien's Group notified the SCC that they are the Qualified Individual and will be coordinating the response for the spill. By 1830Z they had already dispatched MSRC, NRC to the scene with four boom boats and two skimmers. OES, Fish and Game, OSPR, and local stakeholders were contacted by SCC and Sector IMD. SCC dispatched PSC, I/O, and IMD team to the vessel to conduct survey and investigation.

Date/TimeSubject(s)EnteredBy071914ZNOV07COSCO BUSANCooper, Drew P.

Message

VESSEL ANCHORED IN ANCHORAGE 9.

Date/Time Subject(s) Entered By
072000ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

Sector stood up Unified Command at YBI. IMD dispatched SCAT teams to conduct shoreline assessment throughout the afternoon. MSST boats were dispatched to conduct safety zone around the vessel, and enforce the security zone around the bridge abuttments

Date/Time Subject(s) Entered By 072007ZNOV07 UTB - 41392 Boyd, Ryan E.

Message

UTB - 41392 USCG - CG STA SAN FRANCISCO Departed Scene

 Date/Time
 Subject(s)
 Entered By

 072010ZNOV07
 UTB - 41392
 Boyd, Ryan E.

Message

UTB - 41392 USCG - CG STA SAN FRANCISCO Sortie Ended

Date/Time Subject(s) Entered By
072104ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

Briefed ASSF for launch

 Date/Time
 Subject(s)
 Entered By

 072110ZNOV07
 RBS - 25406
 Boyd, Ryan E.

Message

Response Resource Requested

 Date/Time
 Subject(s)
 Entered By

 072110ZNOV07
 RBS - 25406
 Boyd, Ryan E.

Message

RBS - 25406 USCG - CG STA SAN FRANCISCO Launched

Date/Time Subject(s) Entered By 072120ZNOV07 RBS - 25406 Boyd, Ryan E.

Message

RBS - 25406 USCG - CG STA SAN FRANCISCO On Scene at 072120Z NOV 07

Date/Time Subject(s) Entered By 072120ZNOV07 RBS - 25406 Boyd, Ryan E.

Message

Target Located at 072120Z NOV 07

 Date/Time
 Subject(s)
 Entered By

 072120ZNOV07
 RBS - 25406
 Boyd, Ryan E.

Message

RBS - 25406 USCG - CG STA SAN FRANCISCO Alongside

Date/Time Subject(s) Entered By 072130ZNOV07 RBS - 25406 Boyd, Ryan E.

Message

RBS - 25406 USCG - CG STA SAN FRANCISCO Departed Scene

Date/TimeSubject(s)Entered By072138ZNOV07RBS - 25406Boyd, Ryan E.

Message

RBS - 25406 USCG - CG STA SAN FRANCISCO Sortie Ended

 Date/Time
 Subject(s)
 Entered By

 072204ZNOV07
 RBS - 25501
 Boyd, Ryan E.

Message

RBS - 25501 USCG - CG STA SAN FRANCISCO Departed Scene

Date/Time Subject(s) Entered By 072241ZNOV07 UTB - 41392 housey, keith m.

Message

Response Resource Requested

Date/Time Subject(s) Entered By 072241ZNOV07 UTB - 41392 housey, keith m.

Message

UTB - 41392 USCG - CG STA SAN FRANCISCO Launched

Date/Time Subject(s) Entered By
072255ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

ASSF HELO 6516 has experienced a flight casualty and will not be able to land at the confined space at YBI. Directed to RTB.

Date/Time Subject(s) Entered By

072318ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

STA SF UTB has a 10min ETA.

Date/Time Subject(s) Entered By 072333ZNOV07 UTB - 41392 housey, keith m.

Message

UTB - 41392 USCG - CG STA SAN FRANCISCO On Scene at 072333Z NOV 07

Date/TimeSubject(s)Entered By072337ZNOV07<no subject>NAGLE, RUSSELL P.

Message

SCC Updated SMIB to warn mariners to keep a lookout for various amounts of oil and diesel in the water.

watti.

Date/Time Subject(s) Entered By 80000ZNOV07 <no subject> bidowski, andrea.

Message

Issued COTP Order # 07-074.

Date/Time Subject(s) Entered By
080003ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

STA GG Reports NPS is closing their beaches effected by the oil spill. D11 Notified.

Date/Time Subject(s) Entered By
080021ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

Briefed D11 about NPS plans to close beaches

Date/Time Subject(s) Entered By 080121ZNOV07 UTB - 41392 housey, keith m.

Message

UTB - 41392 USCG - CG STA SAN FRANCISCO Sortie Ended

Date/TimeSubject(s)Entered By080202ZNOV07COSCO BUSANFlesher, Gabriel

Α.

Message

VTS SF IRO COTP ORDER 07-074 - COSCO BUSAN to remain in ANC 9 until order is adjusted or rescinded and damage assessment required by VSL's classification society.

Date/Time Subject(s) Entered By
081628ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

CG6516 A/B for overflight

Date/Time Subject(s) Entered By
081758ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

Briefed ASSF for 2nd overflight

Date/Time Subject(s) Entered By
081915ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

SCC ntfd Dl1 of the request for support from the Pacific Strike Team

Date/Time Subject(s) Entered By
081940ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

ASSF picked up SEC SF CO for overflight

Date/Time Subject(s) Entered By

082000ZNOV07 <no subject> NAGLE, RUSSELL P.

Message

SCC ntfd D11 of the incident command post contact numbers

Date/Time Subject(s) Entered By
082214ZNOV07 RBS - 25501 Boyd, Ryan E.

Message

RBS - 25501 USCG - CG STA SAN FRANCISCO Sortie Ended

Date/TimeSubject(s)Entered By090405ZNOV07COSCO BUSANFlesher, Gabriel

Α.

Message

VTS SF IRO COTP ORDER 07-074 Ammendment 01 for COSCO BUSAN. VSL is permitted to depart ANC 9 for OAK 56. VSL required to have 02 tug escort, minimize list while offloading cargo, shall not depart until COTP SF approves repair proposal.

Date/TimeSubject(s)Entered By100200ZNOV07COSCO BUSAN; KELSO, ARNOLDFlesher, Gabriel

Α.

Message

Unit 18 A/B M/V COSCO BUSAN RPTS preparing to depart ANC 9 for OAK 56 IAW COTP Order 07-074.

Date/Time Subject(s) Entered By
100534ZNOV07 <no subject> Grant, Luke J.

Message

100030R - PACAREA - D11 - SEC SAN FRAN - M/V COSCO BUSAN - UPDATE - First light overflights were conducted to determine/assess which areas needed to be skimmed. Eleven skimmers have been actively skimming areas within the affected counties of San Francisco, Marin, Alameda, and Contra Costa. A total of 38,200 feet of boom has been set in these counties with emphasis on 10 known environmentally sensitive sites. Weather conditions continue to promote effective skimming ops inside and outside of the Golden Gate. To date, 8000 to 9500 gallons of product have been recovered. During the last 12 hours, approximately 11,000 gallons of oily water mixture was recovered. Twenty-four shoreline contractor cleanup teams have been employed/assigned at the 22 affected beaches. Seven cubic yards of oily solid material have been collected from impacted beaches. Five Shoreline Cleanup Assessment Teams have been organized and deployed to assess shoreline conditions and provide cleanup recommendations. To date, 94 birds were oiled and are being treated. 28 birds have died. Vessel has safely shifted from Anchorage 9 to Oakland Berth 56. The COTP has detained the vessel under the International Safety Management (ISM) code. Case Pends. V/r, LTJG Grant, LANT/D5 MHLS Watch

Date/TimeSubject(s)Entered By100556ZNOV07COSCO BUSAN; KELSO, ARNOLDFlesher, Gabriel

A.

Message

SF Bar Pilot unit 18 RPTS SUBJ VSL moored Hanjin Terminal Berth 56, Oakland CA.

Date/TimeSubject(s)Entered By110028ZNOV07<no subject>Flesher, Gabriel

Α.

Message

Incident Management Activety 3094631 - Final Review Conducted by OSC G. Flesher (SEC SF - VTS).

QRC's				
□ Allision				
☐ Initial Information				
□ 1. Document Allision Specifics				
2. Is there apparent damage to the structure?				
☐ 3. Is the structure operable?				
4. Are there any restrictions to the waterway?				
5. Are there any restrictions to highway or railroad traffic?				
☐ 6. Is SAR required? (if yes, see #1 below)				
☐ 7. Is incident a serious marine incident, significant marine casualty and/or a major marine				
casualty? If yes, start applicable QRC				
□ 8. Is there any pollution? If yes, start applicable Pollution QRC				
 9. Document information on Person in Charge of Vessel 10. Were there any personnel injuries or deethe? 				
 □ 10. Were there any personnel injuries or deaths? □ Initial Actions 				
☐ 1. Take SAR Action, if applicable (see #6 above)				
☐ a. Action by your unit? If yes, start applicable SAR QRC				
b. Action by other unit?				
☐ 2. Notify cognizant ACT/GRP/MSO (check "No" if not required)				
☐ 3. Notify owner or responsible party of structure, state/county DOT, and state/local policy				
(check "No" if no notifications made)				
☐ 4. Issue UMIB (check "No" if not needed)				
☐ 5. Issue NTM (check "No" if not needed)				
□ 6. Notify District (m), (oan) and (obr) (check "No" if not done)				
 7. Notify Area (m) if allision resulted in closure of waterway or bridge for more than 48 				
hours (check "No" if not required)				

Sequence of Events.

11/10/2007 5:34:00 (Known): 100030R - PACAREA - D11 - SEC SAN FRAN - M/V COSCO BUSAN - UPDATE - First light overflights were conducted to determine/assess which areas needed to be skimmed. Eleven skimmers have been actively skimming areas within the affected counties of San Francisco, Marin, Alameda, and Contra Costa. A total of 38,200 feet of boom has been set in these counties with emphasis on 10 known environmentally sensitive sites. Weather conditions continue to promote effective skimming ops inside and outside of the Golden Gate. To date, 8000 to 9500 gallons of product have been recovered. During the last 12 hours, approximately 11,000 gallons of oily water mixture was recovered. Twenty-four shoreline contractor cleanup teams have been employed/assigned at the 22 affected beaches. Seven cubic yards of oily solid material have been collected from impacted beaches. Five Shoreline Cleanup Assessment Teams have been organized and deployed to assess shoreline conditions and provide cleanup recommendations. To date, 94 birds were oiled and are being treated. 28 birds have died. Vessel has safely shifted from Anchorage 9 to Oakland Berth 56. The COTP has detained the vessel under the International Safety Management (ISM) code. Case Pends. V/r, LTJG Grant, LANT/D5 MHLS Watch

Action Class: Response Communication

Sub-Type: Location:

Subject(s) and Details:

<u>Name</u> <u>Type</u> <u>Status</u> <u>Role</u>

<no subject> Other

Details Filed: None

P

FM: SECTOR SAN FRANCISCO

TO: INFO:

ът

UNCLAS //N16130//

SUBJ: MS/ALLISION/LYNN MARIE/COSCO BUSAN/COSCO BUSAN/COSCO BUSAN/INCIDENT LOCATION, LAT 37 46.0 N LONG 122 18.0 W PERIOD:070840Z NOV 07 - 232037Z NOV 07

- 1. SITUATION.
- A. CURRENT STATUS: OPEN IN PROGRESS
- B. NOTIFICATION: 07 Nov 2007; JOHN COTA VIA VHF/FM (OTHER THAN CHANNEL 16); POB:0 ADULTS:0 CHILDREN:0
- C. NARRATIVE: THE CONTAINER SHIP COSCO BUSAN GOT UNDERWAY FROM OAKLAND BERTH 56 FOR SEA, UNIT ROMEO WAS PILOTING THE SHIP. SECTOR SAN FRANCISCO VESSEL TRAFFIC SERVICE NOTICED THE VESSEL MAKING AN UNUSUAL TURN. TRAFFIC ASKED THE PILOT WHAT HIS INTENTIONS WERE, THE PILOT STATED THAT HE INTENDEDS TO TRANSIT UNDER THE DELTA- ECHO SPAN OF THE BAY BRIDGE. TRAFFIC STATED THAT THE VESSEL WAS ON A HEADING THAT LOOKED UNUSUAL; THE PILOT STATED THAT HIS INSTRUMENTS HAD A DIFFERENT READING. SHORTLY AFTER TRAFFIC WAS CONTACTED BY THE PILOT STATING THAT HE HAD JUST STRUCK THE BRIDGE. VTS SF NTFD THE SECTOR SAN FRANCISCO COMMAND CENTER (SCC) AND THE CALIFORNIA TRANSPORTATION AUTHORITY (CAL TRANS). CAL TRANS DISPATCHED INSPECTORS/ENGINEERS TO THE ALLISION SITE AND RPTD NO DAMAGE TO THE BRIDGE STRUCTURE W/ THE EXCEPTION OF THE FENDERING SYSTEM. FOLLOWING THE ALLISION, COSCO BUSAN PROCEEDED TO SAN FRANCISCO BAY ANCHORAGE (ANC) 7 WHERE SAN FRANCISCO BAR PILOT UNIT "R" WAS RELIEVED BY UNIT "37." 37 LATER PILOTED SUBJ VSL FM ANC 7 TO ANC 9. COTP ORDER 07-074 WAS ISSUED BY COTP SF AND RCVD BY VTS SF REQUIRING COSCO BUSAN TO REMAIN IN ANC 9 UNTIL RELEASED BY COTP ORDER. COTP 07-074 WAS LATER AMMENDED TO PERMIT SUBJ VSL TO DEPART ANCHORAGE FOR THE HANJIN TERMINALS AT THE PORT OF OAKLAND, CA. AS OF 101747U NOV 07 M/V COSCO BUSAN REMAINED MOORED ALONGSIDE OF HANJIN BERTH 56 OAKLAND CA. ACTIVITY CLOSED - SECTOR SAN FRANCISCO / VTS - ACTIVITY #: 3094631

07NOV07: PSC INSPECTORS BOARDED THE VESSEL ALONG WITH IO'S FOR POST-CASUALTY INVESTIGATION OF VESSEL. DURING THE COURSE OF THE INVESTIGATION, PSC INSPECTORS NOTICED POSSIBLE LAPSES IN THE IMPLEMENTATION OF THE BRIDGE SAFETY MANAGEMENT SYSTEM. CONDUCTED EXPANDED ISM EXAM REGARDING BRIDGE MANAGEMENT. INSPECTORS FOUND, THROUGH THE EXAM AND INTERVIEWS WITH VESSEL CREW, THAT THE BRIDGE WAS LIKELY NOT MANNED COMMISERATE WITH THE ENVIRONMENTAL CONDITIONS AT THE TIME OF THE CASUALTY. ALSO, THEY NOTICED THAT THE FIXES WERE NOT PLOTTED AS OFTEN AS REQUIRED. ACCORDING TO THE 3/O WHO WAS ON THE BRIDGE AT THE TIME, HE WAS UNABLE TO COMPLY WITH REQUIREMENTS B/C HE WAS MANNING THE EOT AT THE SAME TIME. VESSEL DETAINED FOR FAILURE TO IMPLEMENT THE ISM. FORM B REQUESTED ISM AUDIT TO BE COMPLETED. - ACTIVITY #: 3095968

D. INVOLVED SUBJECTS:

PERSON NAME: COTA, JOHN DOB: ROLE: OTHER

PERSON NAME: KELSO, ARNOLD DOB: 05 JUN 1951 ROLE: WATCHSTANDER

PERSON NAME: HOBURG, ELLSWORTH F DOB: ROLE: WATCHSTANDER

PERSON NAME: COTA, JOHN DOB: ROLE: RESPONSIBLE PARTY

VESSEL NAME: LYNN MARIE VIN: 1116243 CALL SIGN: FLAG: UNITED STATES OF AMERICA GROSS TONS: 196; LENGTH: 92.2 CLASS/TYPE/SUBTYPE: TOWING VESSEL/GENERAL/ LPOC: NPOC:

VESSEL NAME: COSCO BUSAN VIN: 9231743 CALL SIGN: DPSQ FLAG: GERMANY GROSS TONS: 65131; LENGTH: 901.2 CLASS/TYPE/SUBTYPE: GENERAL DRY CARGO SHIP/CONTAINER SHIP/GENERAL LPOC: LONG BEACH - HANJIN CONTAINER TERMINAL - UNITED STATES NPOC:

VESSEL NAME: COSCO BUSAN VIN: 9231743 CALL SIGN: DPSQ FLAG: HONG KONG GROSS TONS: 65131; LENGTH: 901.2 CLASS/TYPE/SUBTYPE: GENERAL DRY CARGO SHIP/CONTAINER SHIP/GENERAL LPOC: LONG BEACH - HANJIN CONTAINER TERMINAL - UNITED STATES NPOC:

FACILITY NAME: SAN FRANCISCO - OAKLAND BAY BRIDGE; FIN: SF000867;

TYPE/SUBTYPE: BRIDGE/

FACILITY NAME: HANJIN TERMINAL - TTI; FIN: SF000138; TYPE/SUBTYPE: WATERFRONT

FACILITY/ MARPOL RECEPTION, CONTAINER

WATERWAY NAME: ANCHORAGE 9; ACOE:

WATERWAY NAME: SAN FRANCISCO BAY; ACOE:

WEATHER:

NO WEATHER DATA RECORDED IN MISLE

- 2. ACTION TAKEN.
- A. 071630Z NOV 07: SCC RCVD RPT FROM VTS STATING THAT THE M/V COSCO BUSAN HAD STRUCK THE DELTA TOWER OF THE BAY BRIDGE WHILE TRANSITING OUTBOUND FROM OAKLAND. THE VSL IS NOW AT ANCHORAGE 7. VTS REPORTS THEY WILL CONTACT CALTRANS
- B. 071630Z NOV 07: INITIAL NOTIFICATION SF BAR PILOT UNIT R WAS PILOTING THE M/V COSCO BUSAN UNDER THE OAKLAND BAY BRIDGE AND STUCK THE DELTA TOWER OF THE BRIDGE.
- C. 071630Z NOV 07:
- D. 071631Z NOV 07:
- E. 071633Z NOV 07: SEC SF VTS BRIEFED CAL TRANS: ALLISION TO THE EAST SIDE OF THE DELTA TOWER OF THE OAKLAND BAY BRIDGE. REPORTED DAMAGE TO PILEINGS.
- F. 071636Z NOV 07: SCC ISSUED AN SMIB ABOUT THE COSCO BUSAN MAKING CONTACT WITH THE BAY BRIDGE. SMIB WARNED ALL VSLS TO KEEP A 100YRD DISTANCE FROM THE VSL AND TO TRANSIT THE AREA WITH CAUTION. SMIB IS TO BE ISSUED EVERY 15 MINUTES.
- G. 071637Z NOV 07: SU BRIEFED ENS HOPPER
- H. 071640Z NOV 07: SCC BRIEFED MR. SULOUFF AT D11
- I. 071646Z NOV 07: BRIEFED STA SF FOR LAUNCH TO INVESTIGATE DAMAGE TO BRIDGE AND VESSEL
- J. 071648Z NOV 07: PIER DEBRIS AND FUEL IN WATER DID NOT KNOW THE FULL EXTENT OF DAMAGE. RECOMMENDED CONTACT ARMY CORP OF ENGINEERS AND RESPOND TO DEBRIS IN WATER.
- K. 071650Z NOV 07: BRIEFED IMD, MST2 ANDERSON WILL BE DEPARTING TO INVESTIGATE SPILL
- L. 071650Z NOV 07: SCC WAS NOTIFIED BY NRC (REPORT # 853865) THAT THERE WAS OIL IN THE WATER CAUSED BY THE M/V COSCO BUSAN. IMD WAS BRIEFED VIA PHONE.
- M. 071650Z NOV 07: COSCO BUSAN RPTD TO VTS: ANCHORED IN ANCHORAGE 7. N. 071655Z NOV 07: MR HOBURG (SF BARY PILOT UNIT: 37) STATED HE HAD RELIEVED CAPTAIN JOHN COTA (SF BAR PILOT UNIT: R).
- O. 071659Z NOV 07: VTS SF SENT SECURITE BCST TO INFORM VESSELS OF MINIMUM WAKE AROUND COSCO BUSAN IN ANC 7.
- P. 071704Z NOV 07: RESPONSE RESOURCE REQUESTED
- Q. 071704Z NOV 07: UTB 41392 USCG CG STA SAN FRANCISCO LAUNCHED
- 071705Z NOV 07: VTS SF NTFD THE ACOE OF THE DEBRIS IN THE WATER SOUTH OF THE OAKLAND BAY BRIDGE.
- S. 071710Z NOV 07: TUB LYNN MARIE INFORMED VTS THAT THE TUG HAD SPOTTED FUEL AND DEBRIS FROM YERBA BUENA ISLAND TO THE ALPHA TOWER OF THE OAKLAND BAY
- T. 071713Z NOV 07: UTB 41392 USCG CG STA SAN FRANCISCO ON SCENE AT 071713Z NOV 07
- U. 071713Z NOV 07: TARGET LOCATED AT 071713Z NOV 07
- 071713Z NOV 07: UTB 41392 USCG CG STA SAN FRANCISCO ALONGSIDE
- W. 071722Z NOV 07: ACOE STATED THAT THEY WOULD SEND ASSESTS TO ASSIST IN DEBRIS CLEAN UP.
- X. 071722Z NOV 07: CONTACTED AGENT WHO STATED THAT OSRO HAD BEEN NOTIFIED
- 071723Z NOV 07: INQUIRED IF ANY OF THE OIL RESPONSE BOATS HAVE CHECKED IN FOR THE COSCO BUSAN. NO OIL RESPONSE VESSELS HAVE CHECKED IN AS OF YET. VTS QUERRIED THE PILOT ON FUEL LEAKAGE SITUATION. PILOT'S RESPONSE WAS THE SHIP'S CREW HAS SECURED THE FUEL SPILL.
- Z. 071730Z NOV 07: CONDUCTED VIRTUAL BRIEF

- AA. 071739Z NOV 07: CAL TRANS RPTD TO VTS THAT INVESTIGATORS WERE ON SEEN TO CHECK THE STURCTURAL DAMGAE TO THE TOWER.
- AB. 071745Z NOV 07: SCC INITIATED CIC; CIC REQUEST DENIED DUE TO THE ISSUE BEING A LOCAL ISSUE.
- AC. 071745Z NOV 07: PO ANDERSON REPORTS THE SOUNDING TUBE APPEARS BENT; RESULTING IN UNCERTAIN INFORMATION REGARDING FUEL DISCHARGE.
- AD. 071754Z NOV 07: REQUESTED TO SHIFT THE VESSEL TO ANCHORAGE 9 DUE TO DRAFT CONCERNS, THE VESSEL IS DRAWING 40'4" ANCHORAGE 7 IS NOT AN IDEAL ANCHORAGE FOR THE VESSEL. SEC SF SMC AUTHORIZED.
- AE. 071754Z NOV 07: COSCO BUSAN ENR ANCHOARAGE 9
- AF. 071757Z NOV 07: CGC TERN BRIEFED FOR LAUNCH
- AG. 071758Z NOV 07: SEC SF VTS NOTIFIED VSL THAT VESSEL HAD TO MAINTAIN ATLEAST 1 NM DISTANCE FROM ANY ANCHORED VESSEL.
- AH. 071807Z NOV 07: UNIT 37 ONBOARD THE COSCO BUSAN CONTACTED SEC SF VTS PREPARING TO DEPART ANCHORAGE 7 FOR ANCHORAGE 9.
- AI. 071812Z NOV 07: WE RECEIVED A CALL FROM DANNY HEROD AT O'BRIENS STATING THAT AN OSRO TEAM IS GETTING ASSEMBLED.
- AJ. 071817Z NOV 07: RESPONSE RESOURCE REQUESTED
- AK. 071817Z NOV 07: RBS 25501 USCG CG STA SAN FRANCISCO LAUNCHED
- AL. 071822Z NOV 07: NOTIFIED THAT M/V COSCO BUSAN UNDERWAY FOR ANCHORAGE 9
- AM. 071822Z NOV 07: CGC TERN ASSUMES PATCOM
- AN. 071825Z NOV 07: RBS 25501 USCG CG STA SAN FRANCISCO ON SCENE AT 071825Z NOV 07
- AO. 071825Z NOV 07: TARGET LOCATED AT 071825Z NOV 07
- AP. 071825Z NOV 07: RBS 25501 USCG CG STA SAN FRANCISCO ALONGSIDE
- AQ. 071830Z NOV 07: THE O'BRIEN'S GROUP NOTIFIED THE SCC THAT THEY ARE THE QUALIFIED INDIVIDUAL AND WILL BE COORDINATING THE RESPONSE FOR THE SPILL. BY 1830Z THEY HAD ALREADY DISPATCHED MSRC, NRC TO THE SCENE WITH FOUR BOOM BOATS AND TWO SKIMMERS. OES, FISH AND GAME, OSPR, AND LOCAL STAKEHOLDERS WERE CONTACTED BY SCC AND SECTOR IMD. SCC DISPATCHED PSC, I/O, AND IMD TEAM TO THE VESSEL TO CONDUCT SURVEY AND INVESTIGATION.
- AR. 071914Z NOV 07: VESSEL ANCHORED IN ANCHORAGE 9.
- AS. 072000Z NOV 07: SECTOR STOOD UP UNIFIED COMMAND AT YBI. IMD DISPATCHED SCAT TEAMS TO CONDUCT SHORELINE ASSESSMENT THROUGHOUT THE AFTERNOON. MSST BOATS WERE DISPATCHED TO CONDUCT SAFETY ZONE AROUND THE VESSEL, AND ENFORCE THE SECURITY ZONE AROUND THE BRIDGE ABUTTMENTS
- AT. 072007Z NOV 07: UTB 41392 USCG CG STA SAN FRANCISCO DEPARTED SCENE
- AU. 072010Z NOV 07: UTB 41392 USCG CG STA SAN FRANCISCO SORTIE ENDED
- AV. 072104Z NOV 07: BRIEFED ASSF FOR LAUNCH
- AW. 072110Z NOV 07: RESPONSE RESOURCE REQUESTED
- AX. 072110Z NOV 07: RBS 25406 USCG CG STA SAN FRANCISCO LAUNCHED
- AY. 072120Z NOV 07: RBS 25406 USCG CG STA SAN FRANCISCO ON SCENE AT 072120Z NOV 07
- AZ. 072120Z NOV 07: TARGET LOCATED AT 072120Z NOV 07
- BA. 072120Z NOV 07: RBS 25406 USCG CG STA SAN FRANCISCO ALONGSIDE
- BB. 072130Z NOV 07: RBS 25406 USCG CG STA SAN FRANCISCO DEPARTED SCENE
- BC. 072138Z NOV 07: RBS 25406 USCG CG STA SAN FRANCISCO SORTIE ENDED
- BD. 072204Z NOV 07: RBS 25501 USCG CG STA SAN FRANCISCO DEPARTED SCENE
- BE. 072241Z NOV 07: RESPONSE RESOURCE REQUESTED
- BF. 072241Z NOV 07: UTB 41392 USCG CG STA SAN FRANCISCO LAUNCHED BG. 072255Z NOV 07: ASSF HELO 6516 HAS EXPERIENCED A FLIGHT CASUALTY AND WILL NOT BE ABLE TO LAND AT THE CONFINED SPACE AT YBI. DIRECTED TO RTB.
- BH. 072318Z NOV 07: STA SF UTB HAS A 10MIN ETA.
- BI. 072333Z NOV 07: UTB 41392 USCG CG STA SAN FRANCISCO ON SCENE AT 072333Z NOV 07
- BJ. 072337Z NOV 07: SCC UPDATED SMIB TO WARN MARINERS TO KEEP A LOOKOUT FOR VARIOUS AMOUNTS OF OIL AND DIESEL IN THE WATER.
- BK. 080000Z NOV 07: ISSUED COTP ORDER # 07-074.
- BL. 080003Z NOV 07: STA GG REPORTS NPS IS CLOSING THEIR BEACHES EFFECTED BY THE OIL SPILL. D11 NOTIFIED.

- BM. 080021Z NOV 07: BRIEFED D11 ABOUT NPS PLANS TO CLOSE BEACHES
- BN. 080121Z NOV 07: UTB 41392 USCG CG STA SAN FRANCISCO SORTIE ENDED
- BO. 080202Z NOV 07: VTS SF IRO COTP ORDER 07-074 COSCO BUSAN TO REMAIN IN
- ANC 9 UNTIL ORDER IS ADJUSTED OR RESCINDED AND DAMAGE ASSESSMENT REQUIRED BY VSL'S CLASSIFICATION SOCIETY.
- BP. 081628Z NOV 07: CG6516 A/B FOR OVERFLIGHT
- BQ. 081758Z NOV 07: BRIEFED ASSF FOR 2ND OVERFLIGHT
- BR. 081915Z NOV 07: SCC NTFD D11 OF THE REQUEST FOR SUPPORT FROM THE PACIFIC STRIKE TEAM
- BS. 081940Z NOV 07: ASSF PICKED UP SEC SF CO FOR OVERFLIGHT
- BT. 082000Z NOV 07: SCC NTFD D11 OF THE INCIDENT COMMAND POST CONTACT NUMBERS
- BU. 082214Z NOV 07: RBS 25501 USCG CG STA SAN FRANCISCO SORTIE ENDED BV. 090405Z NOV 07: VTS SF IRO COTP ORDER 07-074 AMMENDMENT 01 FOR COSCO BUSAN. VSL IS PERMITTED TO DEPART ANC 9 FOR OAK 56. VSL REQUIRED TO HAVE 02 TUG ESCORT, MINIMIZE LIST WHILE OFFLOADING CARGO, SHALL NOT DEPART UNTIL COTP SF APPROVES REPAIR PROPOSAL.
- BW. 1002002 NOV 07: UNIT 18 A/B M/V COSCO BUSAN RPTS PREPARING TO DEPART ANC 9 FOR OAK 56 IAW COTP ORDER 07-074.
- BX. 100534Z NOV 07: 100030R PACAREA D11 SEC SAN FRAN M/V COSCO BUSAN - UPDATE - FIRST LIGHT OVERFLIGHTS WERE CONDUCTED TO DETERMINE/ASSESS WHICH AREAS NEEDED TO BE SKIMMED. ELEVEN SKIMMERS HAVE BEEN ACTIVELY SKIMMING AREAS WITHIN THE AFFECTED COUNTIES OF SAN FRANCISCO, MARIN, ALAMEDA, AND CONTRA COSTA. A TOTAL OF 38,200 FEET OF BOOM HAS BEEN SET IN THESE COUNTIES WITH EMPHASIS ON 10 KNOWN ENVIRONMENTALLY SENSITIVE SITES. CONDITIONS CONTINUE TO PROMOTE EFFECTIVE SKIMMING OPS INSIDE AND OUTSIDE OF THE GOLDEN GATE. TO DATE, 8000 TO 9500 GALLONS OF PRODUCT HAVE BEEN RECOVERED. DURING THE LAST 12 HOURS, APPROXIMATELY 11,000 GALLONS OF OILY WATER MIXTURE WAS RECOVERED. TWENTY-FOUR SHORELINE CONTRACTOR CLEANUP TEAMS HAVE BEEN EMPLOYED/ASSIGNED AT THE 22 AFFECTED BEACHES. SEVEN CUBIC YARDS OF OILY SOLID MATERIAL HAVE BEEN COLLECTED FROM IMPACTED BEACHES. FIVE SHORELINE CLEANUP ASSESSMENT TEAMS HAVE BEEN ORGANIZED AND DEPLOYED TO ASSESS SHORELINE CONDITIONS AND PROVIDE CLEANUP RECOMMENDATIONS. TO DATE, 94 BIRDS WERE OILED AND ARE BEING TREATED. 28 BIRDS HAVE DIED. VESSEL HAS SAFELY SHIFTED FROM ANCHORAGE 9 TO OAKLAND BERTH 56. THE COTP HAS DETAINED THE VESSEL UNDER THE INTERNATIONAL SAFETY MANAGEMENT (ISM) CODE. CASE PENDS. V/R, LTJG GRANT, LANT/D5 MHLS WATCH
- BY. 100556Z NOV 07: SF BAR PILOT UNIT 18 RPTS SUBJ VSL MOORED HANJIN TERMINAL BERTH 56, OAKLAND CA.
- 3. PLANS AND RECOMMENDATIONS:
- 4. AMPLIFYING INFO:
- 5. SORTIE DATA:
- A. UNIT:USCG CG STA SAN FRANCISCO RESOURCE ID: UTB 41392 RISK ASSESSMENT: GREEN:18 TIME ON SORTIE: 03:06 TIME SEARCHING: 00:00
- B. UNIT:USCG CG STA SAN FRANCISCO RESOURCE ID: RBS 25501 RISK ASSESSMENT: GREEN:16 TIME ON SORTIE: 28:57 TIME SEARCHING: 00:00
- C. UNIT:USCG CG STA SAN FRANCISCO RESOURCE ID: RBS 25406 RISK ASSESSMENT: GREEN:13 TIME ON SORTIE: 00:28 TIME SEARCHING: 00:00
- D. UNIT:USCG CG STA SAN FRANCISCO RESOURCE ID: UTB 41392 RISK ASSESSMENT: GREEN:18 TIME ON SORTIE: 03:40
- 6. MISLE CASE ID:381733
- HTTP://MISLE.OSC.USCG.MIL/MSNWEB/MSN_CASE_DETAIL.ASP?CASE_ID=381733

Case History Report

12 Nov 2007 04:41(Z)

---Administrative Data---

Case #: 381733 Open Dt: 07 Nov 2007

Status: Open - In Progress

Title: MS Allision/ 37 46. N 122 18. W/071630ZNOV07

Originating Unit: SEC SanFran Owner: SEC SanFran Control: SEC SanFran

Other Activities (Non IMA or Non Sortie) in Case:

Activity #: 3095030 Activity Type: Incident Investigation
Activity #: 3095968 Activity Type: Vessel Inspection/PSC

---Incident Data---

• Activity #: 3096205 Status: Open - In Progress Start Dt: 10 Nov 2007

Activity Type: Incident Management

Orig Unit: LANT Owner: LANT Control: LANT

Incident Type: MS
Incident Cause: Allision
Incident Summary:

Involved Subjects:

Attached QRC's:

Type: M Desc: Allision Date added: 11/10/2007 5:34:50 AM Unit added: COMDT 37RCC

Type: M Desc: Bridge Allision Date added: 11/10/2007 5:34:50 AM Unit added: COMDT

37RCC

Type: M Desc: Control of Vessel Movements Date added: 11/10/2007 5:34:50 AM Unit

added: COMDT 385

Type: M Desc: Hazmat Pollution Incidents Date added: 11/10/2007 5:34:50 AM Unit

added: COMDT 3RPP

Type: M Desc: Major Marine Casualties Date added: 11/10/2007 5:34:50 AM Unit added:

COMDT 385

Type: M Desc: MRI Allision Date added: 11/10/2007 5:34:50 AM Unit added: COMDT

385

Type: M Desc: Regional Response Team Notification Date added: 11/10/2007 5:34:50 AM

Unit added: COMDT 3RPP

Type: M Desc: Side Scan Sonar Date added: 11/10/2007 5:34:50 AM Unit added: COMDT

3RPP

Type: M Desc: Significant/Major Marine Casualty Date added: 11/10/2007 5:34:50 AM

Unit added: COMDT 3RPP

Type: M Desc: Vessel Collisions or Groundings Date added: 11/10/2007 5:34:50 AM Unit

added: COMDT 3RPP

• Activity #: 3094822 Status: Open - In Progress Start Dt: 07 Nov 2007

Activity Type: Incident Management

Orig Unit: SEC SanFran Owner: SEC SanFran Control: SEC SanFran

Incident Type: MS
Incident Cause: Allision
Incident Summary:

• Activity #: 3094631 Status: Closed - Agency Action Complete Start Dt: 07

Nov 2007

Activity Type: Incident Management

Orig Unit: SEC SanFran Owner: SEC SanFran Control: SEC SanFran

07 Nov 2007; JOHN COTA VIA VHF/FM (OTHER THAN CHANNEL 16); POB:0 ADULTS:0

CHILDREN:0 Incident Type: MS Incident Cause: Allision

Incident Summary: The container ship Cosco Busan got underway from Oakland berth 56 for sea, unit Romeo was piloting the ship. Sector San Francisco Vessel Traffic Service noticed the vessel making an unusual turn. Traffic asked the pilot what his intentions were, the pilot stated that he intendeds to transit under the Delta- Echo span of the Bay Bridge. Traffic stated that the vessel was on a heading that looked unusual; the pilot stated that his instruments had a different reading. Shortly after traffic was contacted by the pilot stating that he had just struck the bridge. VTS SF NTFD the Sector San Francisco Command Center (SCC) and the California Transportation Authority (CAL TRANS). CAL TRANS dispatched inspectors/engineers to the allision site and RPTD no damage to the bridge structure w/ the exception of the fendering system. Following the allision, COSCO BUSAN proceeded to San Francisco Bay anchorage (ANC) 7 where San Francisco Bar Pilot Unit "R" was relieved by unit "37." 37 later piloted SUBJ VSL FM ANC 7 to ANC 9. COTP Order 07-074 was issued by COTP SF and RCVD by VTS SF requiring COSCO BUSAN to remain in ANC 9 until released by COTP Order. COTP 07-074 was later ammended to permit SUBJ VSL to depart anchorage for the Hanjin Terminals at the Port of Oakland, CA. As of 101747U NOV 07 M/V COSCO BUSAN remained moored alongside of Hanjin Berth 56 Oakland Ca. Activity Closed - Sector San Francisco / VTS

Weather:

Vessel Name: LYNN MARIE VIN: 1116243 Call Sign:

Role: Transiting Vicinity of Primary Subject

Flag: United States of America Gross Tons: 196 Length: 92.2

Completed Dt: 2001

Service: Towing Vessel Propulsion:

Damage Status:

Vessel Name: COSCO BUSAN VIN: 9231743 Call Sign: DPSQ

Role: Acknowledged Pollution Source

Flag: GERMANY Gross Tons: 65131 Length: 901.2

Keel Laid Dt:

Service: Freight Ship Propulsion: Diesel Direct

Damage Status:

Facility Name: San Francisco - Oakland Bay Bridge FIN: SF000867

Type: Bridge

Role: Site of Incident

Facility Name: HANJIN TERMINAL - TTI FIN: SF000138

Type: Waterfront Facility Role: Cargo Transfer Location

Person Name: KELSO, ARNOLD DOB: 05 Jun 1951 Status:

SSN:541-64-6272 Role: Watchstander

Person Name: HOBURG, ELLSWORTH F DOB: Status:

SSN:567-50-5693 Role: Watchstander

Person Name: COTA, JOHN DOB: Status:

IPN/COFR #:IP90008036 Role: Responsible Party

Waterway Name: Anchorage 9 ACOE:

Role: Location

Waterway Name: San Francisco Bay ACOE:

Role: Location

---Sortie Data---

• Activity #: 3095621 Status: Closed - Agency Action Complete Start Dt: 08

Nov 2007

Activity Type: Resource Sortie Start Dt: 08 Nov 2007

Orig Unit: STA SanFran Owner: STA SanFran Control: STA SanFran

Target Location Method: Distance: 0

Mission: Patrol (Non-Security)

Request DtTm: 11/07/2007 10:41:00 PM Request Unit: STA SanFran

Launch DtTm: 11/07/2007 10:41:00 PM

On Scene DtTm: 11/07/2007 11:33:00 PM

Target Loc DtTm: Along Side DtTm: Depart DtTm:

End DtTm: 11/08/2007 1:21:00 AM

Comments:

Weather: Weather DtTm:

Gen Location:

Water Temp: Water Depth: Wave Height: Wind Speed: Wind Gust: Wind Direction: Ceiling: Visibility: Sea Pressure:

Sky Cond: Precip Type:

Results:

People: 0 Outcome: Lives assisted Assistance: Other assistance

Amount: \$13000000 Outcome: Otherwise Assisted

• Activity #: 3095056 Status: Closed - Agency Action Complete Start Dt: 07

Nov 2007

Activity Type: Resource Sortie Start Dt: 07 Nov 2007

Orig Unit: STA SanFran Owner: STA SanFran Control: STA SanFran

Target Location Method: Other method Distance: 1

Mission: Patrol (Non-Security)

Request DtTm: 11/07/2007 6:17:00 PM Request Unit: STA SanFran

Launch DtTm: 11/07/2007 6:17:00 PM

On Scene DtTm: 11/07/2007 6:25:00 PM Target Loc DtTm: 11/07/2007 6:25:00 PM

Along Side DtTm: 11/07/2007 6:25:00 PM
Depart DtTm: 11/07/2007 10:04:00 PM
End DtTm: 11/08/2007 10:14:00 PM

Comments:

Weather:

Weather DtTm: 11/07/2007 6:25:00 PM

Gen Location: SF BAY IVO ANCHORAGE 9

Water Temp: 59 Water Depth: Wave Height: Wind Speed: Wind Gust: Wind Direction: Ceiling: Visibility: 3 Sea Pressure:

Sky Cond: Overcast Precip Type:

Results:

People: 0 Outcome: Lives assisted Assistance: Other assistance

Amount: \$13000000 Outcome: Otherwise Assisted

• Activity #: 3095059 Status: Closed - Agency Action Complete Start Dt: 07

Nov 2007

Activity Type: Resource Sortie Start Dt: 07 Nov 2007

Orig Unit: STA SanFran Owner: STA SanFran Control: STA SanFran

Target Location Method: Other method Distance: 1

Mission: Patrol (Non-Security)

Request DtTm: 11/07/2007 9:10:00 PM Request Unit: STA SanFran

Launch DtTm: 11/07/2007 9:10:00 PM

On Scene DtTm: 11/07/2007 9:20:00 PM Target Loc DtTm: 11/07/2007 9:20:00 PM

Along Side DtTm: 11/07/2007 9:20:00 PM
Depart DtTm: 11/07/2007 9:30:00 PM
End DtTm: 11/07/2007 9:38:00 PM

Comments:

Weather:

Weather DtTm: 11/07/2007 9:20:00 PM

Gen Location: SF BAY IVO ANCHORAGE 9

Water Temp: 59 Water Depth: Wave Height:

Wind Speed: Wind Gust: Wind Direction: Ceiling: Visibility: 3 Sea Pressure:

Sky Cond: Clear Precip Type:

Results:

People: 0 Outcome: Lives assisted Assistance: Other assistance

Amount: \$13000000 Outcome: Otherwise Assisted

• Activity #: 3095046 Status: Closed - Agency Action Complete Start Dt: 07

Nov 2007

Activity Type: Resource Sortie Start Dt: 07 Nov 2007

Orig Unit: STA SanFran Owner: STA SanFran Control: STA SanFran

Target Location Method: Other method Distance: 1

Mission: Patrol (Non-Security)

Request DtTm: 11/07/2007 5:04:00 PM Request Unit: STA SanFran

Launch DtTm: 11/07/2007 5:04:00 PM

On Scene DtTm: 11/07/2007 5:13:00 PM Target Loc DtTm: 11/07/2007 5:13:00 PM

Along Side DtTm: 11/07/2007 5:13:00 PM
Depart DtTm: 11/07/2007 8:07:00 PM
End DtTm: 11/07/2007 8:10:00 PM

Comments:

Weather:

Weather DtTm: 11/07/2007 5:13:00 PM

Gen Location: SF BAY IVO ANCHORAGE 9

Water Temp: 59 Water Depth: Wave Height:

Wind Speed: Wind Gust: Wind Direction: Ceiling: Visibility: 3 Sea Pressure:

Sky Cond: Overcast Precip Type:

Results:

People: 0 Outcome: Lives assisted Assistance: Other assistance

Amount: \$7600000 Outcome: Otherwise Assisted